

Operations & Maintenance Cost Study for NASA Facilities

Final Report for Space Science (R&D and Test) Buildings

March 3, 2014

Submitted to:

Peter Aitcheson
National Aeronautics and Space Administration
300 E Street, SW
Washington, DC 20546-0001

Submitted by:

CBRE | Whitestone
2050 Alameda Padre Serra, STE 200
Santa Barbara, CA 93103-1704

Contract NNC09BA14B

Operations & Maintenance Cost Study for NASA Facilities: Final Report for Space Science (R&D and Test) Buildings

Overview

National Aeronautics and Space Administration (NASA) requires a credible method for estimating the operations and maintenance (O&M) requirements of its facilities.¹ The failure to anticipate future costs can lead to under-funding and diminished service life.

NASA has over 450 buildings totaling 12.6 million GSFT distributed at 24 sites in the selected inventory for this project. It is not cost effective to inspect all facilities, yet NASA needs detailed sustainment and operations estimates to support its budget planning. This project developed cost models for a sample of NASA assets with inventory details collected through site surveys. Estimates were extrapolated by facility type and size and adjusted for location to generate requirements for the selected NASA inventory.

The project employed the MARS Facility Cost Forecast System to provide cost information. Now in its eighth version, MARS is a facility cost modeling tool developed by CBRE | Whitestone and used by many federal and commercial agencies.

Phases 1 and 2 of this project called for inspections of four facility types: Administration Buildings, Propulsion Buildings, Communications Buildings, and Space Science (R&D and Test) Buildings. Eight sample buildings were chosen at two sites: the Goddard Space Flight Center (GSFC) and the Marshall Space Flight Center (MSFC). O&M estimates were generated for all buildings but the scope included formal reports for Administration and Propulsion Buildings only.

Site inspections were conducted by Jacobs Facilities, a long-time CBRE | Whitestone partner experienced in inspecting federal facilities and creating MARS component inventories. A team of three, consisting of an architect, and electrical and mechanical engineers, carried out the facility inspections.

Phase 3 of the project scope included individual reports on the two remaining facility types inspected in the previous phases, Communications and Space Science (R&D and Test) Buildings. This report describes the project methodology and presents final estimates for the Space Science (R&D and Test) Buildings in the NASA inventory.

Project Methodology

Parametric Estimates for Buildings

The project methodology entailed estimating O&M requirements for the selected NASA inventory based on the inspection and modeling of a sample of facilities. The project included four key steps:

1. Validate the existing NASA inventory and develop a sample

¹ Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sewer), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management. Maintenance (also known as sustainment) includes preventative maintenance, minor repair, unscheduled maintenance, and renewal and replacement.

2. Perform on-site inspections of the sample buildings
3. Develop and calibrate MARS models
4. Generate per square foot estimates of sustainment and operations costs for the sample and extrapolate to the project inventory

Study Sample

NASA has over 450 buildings at 24 sites globally in the selected inventory. Complete inspection of each site to estimate O&M requirements is impractical and costly. This project generated sustainment and operations estimates for a sample of buildings and extrapolated the costs to a selected NASA inventory.

The Statement of Work called for a sample that included one small building (approximately 10,000 square feet) and one large building (approximately 100,000 square feet) from four Classification types. The sample included two buildings from Administration Buildings, Propulsion Buildings, Communications Buildings, and Space Science (R&D and Test) Buildings. Phases 1 and 2 of the project inventory excluded other Classification types in the NASA inventory, such as Warehouses and Wind Tunnels. CBRE | Whitestone proposed buildings at the Goddard Space Flight Center and the Marshall Space Flight Center to minimize travel costs.

Table 1 shows the building detail for the inspected Space Science (R&D and Test) Buildings.

Table 1. Space Science (R&D Test) Buildings Inspection Sample

Site	Classification	Property ID	Property Name	Year Built	Size	CRV
Goddard Space Flight Center	Space Science (R&D & Test Buildings)	1019/51/121	B-ATTITUDE CONTROL LAB BLDG/MTS	1964	8,360	\$10,712,733
Goddard Space Flight Center	Space Science (R&D & Test Buildings)	1019/51/50	B-CENTRAL FLIGHT CONTROL/RANGE BLDG	1961	113,961	\$41,722,280
Total					122,321	\$52,435,013

There are a number of variables that drive O&M costs. The project sampling plan only controls for size and Classification type. An alternative sample may control for current replacement value (CRV), age, and location.

The inspected sample was mapped to the remaining inventory by size and type. The 8k gross square foot (GSFT) building was mapped to the smaller half of the inventory, while the 114k GSFT building was mapped to the larger half. Square foot estimates were generated by MARS and then extrapolated to the inventory. All costs were indexed for location.

Space Science (R&D and Test) Buildings represent 16.2 percent of the selected NASA inventory, totaling 2.0 million GSFT and 85 buildings with a \$909.4 million CRV. Table 2 shows the Space Science (R&D and Test) Buildings inventory by Site.

Table 2. NASA Space Science (R&D Test) Buildings by Site

Site	Count	Size	CRV
AMES Research Center	5	126,894	\$71,450,230
Dryden Flight Research Center	1	4,559	\$197,901
Glenn Research Center	4	45,923	\$16,928,476
Goddard Space Flight Center	14	700,852	\$241,907,236
Jet Propulsion Laboratory	50	898,228	\$455,054,068
Johnson Space Center	3	86,379	\$30,047,278
Langley Research Center	2	28,535	\$37,504,861
Marshall Space Flight Center	3	45,800	\$11,355,111
NASA/JSC/White Sands Test Facility	1	3,276	\$157,001
Stennis Space Center	1	90,080	\$44,105,994
Wallops Flight Facility	1	1,635	\$685,738
Total	85	2,032,161	\$909,393,894

Detailed cost models were developed for the two buildings using CBRE | Whitestone's MARS Facility Cost Forecast System.

Description of the MARS Model

CBRE | Whitestone used MARS to estimate preventative maintenance, unscheduled maintenance, repair, and renewal/replacement costs for this project. MARS is an asset management system that estimates both deferred maintenance and future requirements on the basis of asset components and their scheduled maintenance and repair. It also estimates costs for ten operations types in the typical commercial chart of accounts. MARS was originally developed in 1996, and is currently in its eighth version. It is used by many government agencies and commercial concerns.

Sustainment	Preventive Maintenance & Minor Repair Unscheduled Maintenance Renewal & Replacement
Operations	Custodial Energy Grounds Management Pest Control Refuse Road Clearance Security Telecom Water/Sewer

Note that the definition of future M&R requirements is the same as the “sustainment” requirements used for programming by DoD and an approach endorsed in a National Research Council (NRC) study of Department of Energy facility practices.² Among other agencies, the MARS Facility Cost Forecast System has been used to forecast budgets for the IRS, FAA, USDA, and CDC. It was recently used to benchmark costs for the Department of State Overseas Embassies. MARS is also the basis for the DoD Sustainment Model and a study for NNSA validating total life-cycle facility costs at eight nuclear weapons production and research sites.³ The model is used continuously to simulate alternative facility costs for the U.S. nuclear complex.

The MARS process begins with a component inventory of a building or structure. Derived from building plans, equipment inventory data, and on-site inspections, these components are organized into UNIFORMAT category level three elements and are identified specifically in terms of product characteristics, quantity, and output level; e.g. “Single-Ply Modified Bituminous/Thermoplastic Roof,” “Condenser, Air-Cooled, 60 Ton,” or “Pipe & Fittings, ¾” Copper.”

Once the component inventory is completed, the MARS system relates maintenance tasks from a pre-defined task library to each selected component. New components and related tasks are defined as necessary. The frequency of each task determines the forecast of future required maintenance. MARS estimates four types of maintenance: preventative maintenance, unscheduled maintenance (service calls), repair, and renewal/replacement tasks. Tasks and their labor and material requirements are pre-defined by CBRE | Whitestone, but are also editable.


Other calibration steps include modifying default values for contract and in-house labor rates, specifying site-typical mark-up for contract expenditures, and identifying the utilization characteristics for each asset.

The sources for local wage rates and benefits are primarily the U.S. Department of Labor and Davis-Bacon Act labor agreements, and private sector employers. Both union and non-union wages are considered in determining prevailing rates by locality. State and local wage surveys are also used when available.

² National Research Council, *Intelligent Sustainment and Renewal of Department of Energy Facilities and Infrastructure*, 2004. P. 44.

³ Jacobs Facilities and Whitestone Research, *Implementation of the Department of Defense Sustainment Model, Final Report*, May 2002.

MARS Facility Cost Forecast System



MARS is also used to estimate operations costs other than maintenance and repair. These are based on the Facilities Operation Model developed jointly by the Department of Defense (DOD) and CBRE | Whitestone. This model provides costs for ten services, including those mentioned in the Federal Real Property Council (FRPC) guidance—utilities, cleaning and janitorial, and roads and grounds.⁴ Each operation type for an asset can be calibrated for a level of service (low, medium, high) to reflect the level of demand or frequency at which certain operations task are performed.

The CBRE | Whitestone operations cost models provides estimates for the following services:

Custodial. The custodial function represents the expense of cleaning offices, work areas, restrooms and common areas. Costs include local wage rates and benefits, task productivity, mark-ups for equipment, materials, supervision, and assumptions concerning the level of service. Trash removal costs are not included. Custodial service levels are defined by altering the combination and frequency of common tasks.

Energy. Energy includes all expenses related to the purchase, generation, distribution, and conservation of energy and source fuels necessary to operate an asset. The main energy sources considered are electricity and natural gas. Not included are utilities maintenance and supervision, and utility tax rates. Service levels vary according to estimated commodity demand by asset use type.

Grounds. The grounds function includes any expense related to the maintenance of exterior landscaping. It does not include sweeping or the maintenance of signage, parking lots and roadways. Costs are estimated using local wage rates and benefits,

⁴ Federal Real Property Council. *Guidance for Real Property Inventory Reporting*. Washington, D.C. August, 2012.

task productivity, mark-ups for equipment, materials and supervision, and assumptions concerning the level of service. Service levels are defined by altering the combination and frequency of common tasks.

Management. The real property management function describes all costs associated with facility management, including: public works, contracts, material procurement, facility data, furnishings, real estate, and engineering services. Costs are expressed as a fixed percentage of Plant Replacement Value. Service levels are based on the distribution of costs found in institutional and commercial settings. For this project, the level of service for all NASA buildings was set to low to reflect economies of scale in a campus environment.

Pest Control. Pest control expenses cover indoor and outdoor pest control programs, separate from the grounds function. Costs are based on the frequency of common tasks for rodent and insect abatement and inspections. Costs include prevailing labor and material rates. Service levels are defined by altering the combination and frequency of common tasks.

Refuse. Refuse costs include all expenses related to trash collection and disposal, pick-up services, fees, recycling operations and administration, composting, etc. Costs exclude handling and disposal of HAZMAT materials. Service levels vary according to estimated demand by asset use type.

Road Clearance. The road clearance function includes all expenses related to sweeping paved areas including sidewalks, walkways, and parking lots. Costs include prevailing labor and material rates, and climatic variables. Service levels are defined by altering the combination and frequency of common tasks.

Security. Security expenses relate to the physical security of assets and occupants, and include personnel, operating and monitoring security equipment. Costs include relevant prevailing labor and material rates. Service levels are defined by altering the combination and frequency of common tasks and services.

Telecommunications. Telecommunication expenses cover the purchase of all the services ordinarily associated with commercial activities, such as voice and data equipment and service subscription. The level of telecommunications is defined by the combination of services selected.

Water and Sewer. Water and Sewer expenses include all costs related to providing the asset with potable water, irrigation water, and sewage service. Estimates include local commodity costs. Service levels vary according to estimated commodity demand by asset use type.

Data Collection and Calibration

MARS Model Development

The technical work for this task involved the definition of the component inventory for the two sample Space Science (R&D and Test) Buildings. Goddard Space Flight Center staff supplied

existing equipment inventories and construction design documents before the inspection. Jacobs Facilities inspected the buildings and created draft models in MARS. In total, 451 MARS components were defined for the two facilities.

Jacobs submitted the MARS database to CBRE | Whitestone for a detailed component-by-component review. Three areas of focus included:

- 1) Check for completeness. Review the wall finishes (exterior and interior), roofing, plumbing, HVAC, fire protection, and electrical data to ensure the building model contains the appropriate components in each category.
- 2) Check for consistency. Review the building gross square feet for accuracy. Ensure the square footage of structural components (exterior walls, roofing system, interior finishes) are reasonable compared to building GSFT. Verify the capacity of the following is consistent with the building type and size:
 - Heating, cooling, and air distribution
 - Electrical service, distribution, and lighting
 - Plumbing fixtures and water distribution
 - Fire protection
- 3) Forecast review. Run the following building-level MARS reports and look for extraordinary costs (high or low) illustrating an error in the building model:
 - Average M&R Costs
 - Most Costly M&R Tasks
 - Deferred Maintenance Detail
 - Operation Cost Summary

We also compared the costs with known resources (*The Whitestone Facility Maintenance and Repair and Operations Cost References*, comparable CBRE | Whitestone project work with federal agencies, and third party sources).

Attachment A and B provide detailed MARS component lists for the two inspected Space Science (R&D and Test) Buildings at GSFC.

CBRE | Whitestone also collected information to calibrate the models for local site values.

Local Calibration of MARS

While the MARS system has pre-defined building models, labor and material costs, utility rates, and an extensive component library, all of these values can be changed or supplemented to reflect the actual site practices.

Calibration data was gathered to adjust MARS factors at both the site and the building level. Site-level information, such as labor and utility rates, was directly used to estimate O&M costs for the remaining non-inspected buildings at GSFC and MSFC.

Building-level calibration data was applied to the sample models and then extrapolated to the remaining NASA inventory by Classification type and size.

The following data was collected to calibrate the building models:

Maintenance and Repair. The sites provided contract labor rates and labor rate mark-ups. A default assumption in MARS assigns in-house labor to preventative maintenance, minor repair, and unscheduled maintenance, while contract labor performs major repair and replacement tasks. Goddard Space Flight Center and the Marshall Space Flight Center staff indicated all maintenance was performed by contract laborers. CBRE | Whitestone adjusted the MARS database accordingly.

NASA personnel specified laborers must be paid prevailing wages for the area. We used the default MARS wage rates for this study, and included a 30 percent mark-up for contract overhead.

Table 3 shows the source of the maintenance and repair factors for each site.

Table 3. Data Sources by Site, Maintenance & Repair					
Site	In-house Shop Rates	In-house Markup Rates	Contract Labor Rates	Contract Overhead Rates	Utilization
Goddard Space Flight Center	N/A	N/A	WST	WST	Site
Marshall Space Flight Center	N/A	N/A	WST	WST	Site
WST = Whitestone, Site = Respective NASA Site, N/A = Not applicable, no in-house maintenance staff					

MARS estimates also can be adjusted to reflect utilization factors that impact M&R. For example, many NASA facilities have special safety requirements which increase costs relative to conventional commercial practice. Other special requirements include high or low hours of operation and security. The two sites defined utilization factors for the eight building sample in Phases 1 & 2.

Table 4 displays the average utilization multipliers by site used to adjust for these requirements.

Table 4. Average Utilization Adjustment by Site^A

Site	Hours of Operation ^B	Safety & Security ^C	Permitting ^D	Sum ^E
Goddard Space Flight Center	1.37	1.05	1.04	1.45
Marshall Space Flight Center	1.07	1.01	1.03	1.11

^A Calculated from individual asset multipliers assigned by the sites.
^B Hours of Operation rates building use on a weekly basis and is defined as follows: 0.80 = 40 hours, 1.00 = 41 to 80 hours, 1.37 = 80+ hours.
^C Security is defined as follows: 1.00 = free access, 1.01 = contractor training & daily check-in, 1.15 = full contractor accompanyment.
^D Safety & Permitting is defined as follows: 1.00 = typical commercial & service activity, 1.07 = non-specific laboratory, 1.75 = radiological or life science research, 3.00 = nuclear facility.
^E In combination the multipliers are additive such that the total multiplier = $1 + \sum (\beta - 1)$ where β = the multiplier value.

Operations. MARS also estimates operations costs for ten services including: custodial, energy, grounds, management, pest control, refuse, road clearance, security, telecommunications, and water & sewer. We requested utility rates, operations labor rates, and mark-ups. In addition, individual building models are calibrated in terms of level of service (low, medium, high, or none).

Each site defined levels of service for all operation types and provided several utility rates. As with M&R, CBRE | Whitestone used the default MARS wage rates and a 30 percent mark-up for contract overhead.

The utility rates provided by the two sites were significantly lower than the default MARS commercial rates. These discounts are often provided to large federal property holders like NASA. CBRE | Whitestone applied the average discounts for the calibrated sites (GSFC and MSFC) to the remaining sites in the inventory.

Table 5 shows the source of the operations calibration data.

Table 5. Data Sources by Site, Operations

Site	Level of Service	Custodial Wage	Refuse Rates	Energy Rates	Water/Sewer Rates	Groundskeeper Wage	Pest Control Wage	Road Clearance Wage	Security Rates	Property Management	Telecom Rates
Goddard Space Flight Center	Site	WST	Site	Site	Site	WST	WST	WST	WST	Site	WST
Marshall Space Flight Center	Site	WST	WST	Site	Site	WST	WST	WST	WST	Site	WST
WST=Whitestone, Site = Respective NASA Site											

Cost Estimates for Space Science (R&D and Test) Buildings

Sustainment Costs

The final sustainment estimate for the smaller GSFC Space Science (R&D and Test) Building (Property ID 1019/51/121) is an average of \$7.19 per GSFT over a 50-year period. The larger building (Property ID 1019/51/50) is \$9.35 per GSFT over the same period.

The sample estimates were extrapolated to the population. Table 6 shows sustainment costs by site for all Space Science (R&D and Test) Buildings. Sustainment estimates are expressed as 30, 40, and 50-year averages. While CBRE | Whitestone computes annual requirements, average costs are presented to smooth the annual oscillations. Overall, the sustainment requirements are an average of \$17.4 million per year over 50 years, or \$8.56 per GSFT. Expressed another way, this amounts to 1.9 percent of the \$909.4 million replacement value.

Table 6. Average Annual Estimates of Sustainment Requirements by Site, Space Science (R&D Test) Buildings

Site	GSFT	CRV	Sustainment ^A								
			30-Year Estimates			40-Year Estimates			50-Year Estimates		
			Avg. Annual Estimate	Per GSFT	Percent CRV	Avg. Annual Estimate	Per GSFT	Percent CRV	Avg. Annual Estimate	Per GSFT	Percent CRV
AMES Research Center	126,894	\$71,450,230	\$1,319,945	\$10.40	1.8%	\$1,250,587	\$9.86	1.8%	\$1,234,345	\$9.73	1.7%
Dryden Flight Research Center	4,559	\$197,901	\$39,724	\$8.71	20.1%	\$37,156	\$8.15	18.8%	\$34,568	\$7.58	17.5%
Glenn Research Center	45,923	\$16,928,476	\$369,081	\$8.04	2.2%	\$345,229	\$7.52	2.0%	\$321,181	\$6.99	1.9%
Goddard Space Flight Center	700,852	\$241,907,236	\$6,442,474	\$9.19	2.7%	\$6,146,787	\$8.77	2.5%	\$6,254,927	\$8.92	2.6%
Jet Propulsion Laboratory	898,228	\$455,054,068	\$8,285,881	\$9.22	1.8%	\$7,841,689	\$8.73	1.7%	\$7,701,225	\$8.57	1.7%
Johnson Space Center	86,379	\$30,047,278	\$710,354	\$8.22	2.4%	\$676,082	\$7.83	2.3%	\$680,705	\$7.88	2.3%
Langley Research Center	28,535	\$37,504,861	\$199,785	\$7.00	0.5%	\$186,874	\$6.55	0.5%	\$173,857	\$6.09	0.5%
Marshall Space Flight Center	45,800	\$11,355,111	\$322,769	\$7.05	2.8%	\$301,909	\$6.59	2.7%	\$280,879	\$6.13	2.5%
NASA/JSC/White Sands Test Facility	3,276	\$157,001	\$21,717	\$6.63	13.8%	\$20,314	\$6.20	12.9%	\$18,899	\$5.77	12.0%
Stennis Space Center	90,080	\$44,105,994	\$700,463	\$7.78	1.6%	\$668,738	\$7.42	1.5%	\$682,351	\$7.57	1.5%
Wallops Flight Facility	1,635	\$685,738	\$11,447	\$7.00	1.7%	\$10,708	\$6.55	1.6%	\$9,962	\$6.09	1.5%
Total^B	2,032,161	\$909,393,894	\$18,423,641	\$9.07	2.0%	\$17,486,074	\$8.60	1.9%	\$17,392,897	\$8.56	1.9%

^A Sustainment is the average annual sum of preventative maintenance, unscheduled maintenance, and major repair and replacement tasks.

^B All costs expressed in \$2012.

Operation Costs

Final estimates of ten operation costs are shown in Table 7. In total, the operation requirements for the selected Space Science (R&D and Test) Buildings are an annual average of \$19.5 million, or \$9.61 per GSFT and 2.1 percent of replacement value. Note that in commercial accounting M&R (sustainment) is often included as an operating cost, but is reported separately above.

Table 7. Annual Estimates of Operations Costs by Site, Space Science (R&D Test) Buildings

Site	Operations Type ^A												Per GSFT	Percent CRV	
	GSFT	CRV	Custodial	Energy	Grounds	Management	Pest Control	Refuse	Road Clearance	Security	Telecom	Water/Sewer	Total Costs		
AMES Research Center	126,894	\$71,450,230	\$276,373	\$262,490	\$22,160	\$178,626	\$8,123	\$4,609	\$0	\$312,090	\$142,725	\$23,986	\$1,231,182	\$9.70	1.7%
Dryden Flight Research Center	4,559	\$197,901	\$8,464	\$5,637	\$841	\$495	\$189	\$154	\$0	\$12,554	\$491	\$964	\$29,789	\$6.53	15.1%
Glenn Research Center	45,923	\$16,928,476	\$78,799	\$51,125	\$4,881	\$42,321	\$1,555	\$407	\$3,678	\$128,477	\$4,944	\$11,283	\$327,471	\$7.13	1.9%
Goddard Space Flight Center	700,852	\$241,907,236	\$1,769,314	\$1,948,927	\$88,092	\$604,768	\$41,052	\$23,067	\$10,836	\$1,637,954	\$1,221,161	\$235,066	\$7,580,237	\$10.82	3.1%
Jet Propulsion Laboratory	898,228	\$455,054,068	\$1,829,924	\$1,791,534	\$165,610	\$1,137,635	\$37,287	\$30,317	\$0	\$2,050,317	\$925,243	\$190,000	\$8,157,867	\$9.08	1.8%
Johnson Space Center	86,379	\$30,047,278	\$139,847	\$180,314	\$10,498	\$75,118	\$3,505	\$2,616	\$0	\$162,630	\$131,237	\$18,200	\$723,966	\$8.38	2.4%
Langley Research Center	28,535	\$37,504,861	\$42,781	\$29,735	\$3,134	\$93,762	\$1,269	\$891	\$173	\$75,813	\$3,072	\$4,488	\$255,119	\$8.94	0.7%
Marshall Space Flight Center	45,800	\$11,355,111	\$68,481	\$69,297	\$5,739	\$28,388	\$1,317	\$1,520	\$105	\$134,464	\$4,931	\$4,159	\$318,401	\$6.95	2.8%
NASA/JSC/White Sands Test Facility	3,276	\$157,001	\$4,888	\$3,395	\$314	\$393	\$140	\$52	\$23	\$8,479	\$353	\$182	\$18,219	\$5.56	11.6%
Stennis Space Center	90,080	\$44,105,994	\$176,272	\$220,994	\$10,641	\$110,265	\$3,188	\$2,625	\$0	\$170,046	\$162,271	\$8,643	\$864,944	\$9.60	2.0%
Wallops Flight Facility	1,635	\$685,738	\$2,451	\$2,511	\$180	\$1,714	\$73	\$160	\$10	\$4,344	\$176	\$546	\$12,165	\$7.44	1.8%
Total^B	2,032,161	\$909,393,894	\$4,397,596	\$4,565,959	\$312,090	\$2,273,485	\$97,699	\$66,417	\$14,826	\$4,697,168	\$2,596,602	\$497,519	\$19,519,360	\$9.61	2.1%

^A Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sewer), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management.

^B All costs expressed in \$2012.

Total O&M Costs

Estimated total annual Space Science (R&D and Test) Building costs are shown in Table 8. A combination of maintenance and repair (sustainment) and operations, these costs represent an annual average for the next 50 years. Total costs are an estimated \$36.9 million per year, or can also be expressed as \$18.16 per GSFT and 4.1 percent of CRV.

Table 8. Total Annual Costs by Site, Space Science (R&D Test) Buildings

Site	O&M Estimates					Per GSFT	Percent CRV
	GSFT	CRV	50-Year Avg. Sustainment ^A	Annual Operations ^B	Total Costs		
AMES Research Center	126,894	\$71,450,230	\$1,234,345	\$1,231,182	\$2,465,527	\$19.43	3.5%
Dryden Flight Research Center	4,559	\$197,901	\$34,568	\$29,789	\$64,357	\$14.12	32.5%
Glenn Research Center	45,923	\$16,928,476	\$321,181	\$327,471	\$648,652	\$14.12	3.8%
Goddard Space Flight Center	700,852	\$241,907,236	\$6,254,927	\$7,580,237	\$13,835,164	\$19.74	5.7%
Jet Propulsion Laboratory	898,228	\$455,054,068	\$7,701,225	\$8,157,867	\$15,859,091	\$17.66	3.5%
Johnson Space Center	86,379	\$30,047,278	\$680,705	\$723,966	\$1,404,671	\$16.26	4.7%
Langley Research Center	28,535	\$37,504,861	\$173,857	\$255,119	\$428,975	\$15.03	1.1%
Marshall Space Flight Center	45,800	\$11,355,111	\$280,879	\$318,401	\$599,280	\$13.08	5.3%
NASA/JSC/White Sands Test Facility	3,276	\$157,001	\$18,899	\$18,219	\$37,118	\$11.33	23.6%
Stennis Space Center	90,080	\$44,105,994	\$682,351	\$864,944	\$1,547,295	\$17.18	3.5%
Wallops Flight Facility	1,635	\$685,738	\$9,962	\$12,165	\$22,126	\$13.53	3.2%
Total^C	2,032,161	\$909,393,894	\$17,392,897	\$19,519,360	\$36,912,257	\$18.16	4.1%

^A Sustainment is the average annual sum of preventative maintenance, unscheduled maintenance, and major repair and replacement tasks.

^B Operations include custodial (cleaning, pest control, and trash collection), utilities (energy, water, and sewer), grounds (landscape care, mowing, and snow removal), security, telecommunications, and management.

^C All costs expressed in \$2012.

Included in Attachment A and B are detailed MARS reports for the two sample Goddard Space Flight Center Space Science (R&D and Test) Buildings.

**Attachment A: Detailed MARS Reports for GSFC Property ID
1019/51/121**

Building Component List

Whitestone Research

Building: B-Attitude Control Lab Bldg/MTS

Year Built: 1964

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/121

City: Washington, D.C.

Replacement Value: \$10,712,733

per SF: \$1,281

Building Gsft: 8,360

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B1010		Concrete Ramp	1964	160 Sq Ft		
B2010		Aluminum Louver, 1st Floor	1964	2 Each		
B2010		Concrete Block, Exterior, 1st Floor	1964	11704 Sq Ft		
B2020		Aluminum Fixed Window, 24 sf, 1st Floor	1964	12 Each		
B2020		Aluminum Operable Window, 12 sf, 1st Floor	1964	1 Each		
B2030		Sliding, Motor-Operated, Exterior Door	1964	1 Each		
B2030		Wood, Solid Core, Painted, Exterior Door	1964	2 Each		
B3010		Aluminum Gutter, Downspouts, Fittings	1964	0.55 K Ln Ft		
B3010		Single-Ply Modified Bituminous/Thermoplastic Roof	1964	3450 Sq Ft		
B3010		Single-Ply Roof w/ Thermoplastic Olefin (TPO) Membrane	2008	1656 Sq Ft		
C1020		Wood, Solid Core, Painted, Interior Door	1964	1 Each		
C2010		Concrete, Exterior Stairs	1964	30 Sq Ft		
C2010		Metal, Painted, Exterior Railing	1964	72 Ln Ft		
C2010		Wood, Interior Railing	1964	120 Ln Ft		
C2010		Wood, Painted, Interior Stairs	1964	180 Sq Ft		
C3010		Concrete Block, Painted, Interior Wall Finish	1964	4650 Sq Ft		
C3010		Wood, Finished, Interior Paneling	1964	15220 Sq Ft		
C3020		Concrete, Painted Flooring	1964	5500 Sq Ft		
C3020		Wood Decking	1972	3644 Sq Ft		
C3030		Wood, Finished Ceiling	1964	5500 Sq Ft		
D3020		Ball Valve, 2"	1972	3 Each		
D3020		Pipe & Fittings, 1" Steel	1972	0.1 K Ln Ft		
D3020		Pipe Insulation, Fiberglass, Heating Water/Steam	1972	0.1 K Ln Ft		
D3030		Flow Control Valve, Motorized, 2"	1972	4 Each		
D3030		Pipe & Fittings, 2" Steel	1972	0.15 K Ln Ft		
D3030		Pipe Insulation, Fiberglass, Chilled Water	1972	0.15 K Ln Ft		
D3040		Air Handler, Single Zone, 15,000 Cfm	1998	1 Each		
D3040		Duct Insulation, Fiberglass Blanket	1972	1460 Sq Ft		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

04-Dec-13

All costs expressed in (\$) 2012.

Page 1

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
D3040		Ductwork	1972	1748 Lbs		
D3040		Exhaust Fan, Centrifugal, 16,000 Cfm	1998	1 Each		
D3040		Steel Damper, Motorized	1972	2 Each		
D3050		Secondary Coil, 24" x 36"	1972	2 Each		
D3060		HVAC Control Panel	1998	1 Each		
D3060		Thermostat	1998	2 Each		
D4010		Fire Department Connection, Siamese, 3"	1990	2 Each		
D4010		Fire Sprinkler Head	1990	64 Each		
D4010		Fire Sprinkler System	1990	1 Each		
D4010		Pipe & Fittings, 2" Steel	1990	0.316 K Ln Ft		
D4010		Valves & Components, Sprinkler System, 3"	1990	3 Each		
D5010		Disconnect Switch, 100 Amp.	1964	1 Each		
D5010		Disconnect Switch, 100 Amp.	1985	1 Each		
D5010		Disconnect Switch, 30 Amp.	1964	1 Each		
D5010		Disconnect Switch, 60 Amp.	2005	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1964	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 225 Amp	2005	1 Each		
D5010		Power Panel Board, 480 V, 200 Amp.	2005	1 Each		
D5010		Secondary Transformer, Dry, 30 kVA	1964	1 Each		
D5020		Compact Fluorescent Lighting Fixture, 32 w	1995	7 Each		
D5020		Emergency Lighting Pack, 2 Light w/ Battery	1995	1 Each		
D5020		Incandescent Lighting Fixture, Basic, 200 w	1964	14 Each		
D5020		Incandescent Lighting Fixture, EP, 200 w	1964	15 Each		
D5020		Receptacle, 120 V, 15 Amp.	1990	25 Each		
D5020		Wiring Device, Switch	1990	8 Each		
D5030		Annunciation Panel	1990	1 Each		
D5030		Fire Alarm Bell, 6"	2000	2 Each		
D5030		Manual Pull Station	2000	2 Each		
D5030		Smoke Detector	1990	5 Each		
D5030		Smoke Detector, Duct	1990	2 Each		
D5090		Lightning Protection System	1964	0.5 K Ln Ft		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Average M&R Costs

Whitestone Research

	B-Attitude Control Lab Bldg/MTS	GSFT: 8,360
Building Number:	1019/51/121	PRV: \$10,712,733
Facility:	Goddard Space Flight Center	Built Date: 1964
City:	Washington, D.C.	

M&R Average Annual Cost Forecasts

	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$7,424	\$14,184	\$11,821	\$11,766
Unscheduled Maintenance:	\$4,044	\$11,014	\$7,870	\$7,857
Renewal & Replacement:	\$51,901	\$46,638	\$29,571	\$40,475
Total M&R Costs:	\$63,369	\$71,836	\$49,262	\$60,098
Per GSFT:	\$7.58	\$8.59	\$5.89	\$7.19
As % of PRV:	0.59%	0.67%	0.46%	0.56%

M&R Costs by System per Year Chart

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Building Num: 1019/51/121


Facility: Goddard Space Flight Center

GSFT: 8360

City: Washington, D.C.

Forecast Year: 2013 4 5 6 7 2018 9 0 1 2 2023 4 5 6 7 2028 9 0 1 2 2033 4 5 6 7

A10 Foundations																									
A20 Basement Construction																									
B10 Super Structure		0.03													0.04										
B20 Exterior Enclosure	0.06	13.29	0.05	0.05	0.05	0.05	0.09	0.06	0.05	0.05	0.05	9.46	0.05	0.05	0.06	0.05	0.09	0.05	0.05	0.05	0.05	7.50	0.05	0.05	
B30 Roofing	0.26	1.45	0.22	0.22	0.22	0.32	0.30	0.22	0.22	0.22	0.26	4.95	0.22	0.22	0.22	0.32	0.30	0.22	0.22	0.22	0.26	1.45	0.22	0.22	
C10 Interior Construction		0.07		0.00			0.01	0.00				0.07			0.00	0.01			0.00		0.07		0.00		
C20 Stairs		1.56			0.04						0.04	0.61		0.04		0.02	0.04					0.08			
C30 Interior Finishes		9.63		0.57						0.69	7.50			0.57				5.69	7.34			0.57			
D10 Conveying																									
D20 Plumbing																									
D30 HVAC	6.44	0.53	0.53	0.53	1.33	2.11	0.53	0.54	0.53	1.05	2.01	0.53	0.53	0.53	6.60	0.53	0.53	0.53	1.96	0.57	0.53	0.53	0.53	0.56	
D40 Fire Protection	0.55	0.57	0.56	0.55	0.55	0.55	0.55	1.16	0.55	0.55	0.55	0.55	0.57	0.55	0.55	0.55	0.55	0.55	2.96	0.55	0.55	0.55	0.55	0.55	
D50 Electrical	0.27	1.58	0.71	0.25	0.27	0.25	0.35	0.83	0.27	0.25	0.27	5.38	0.51	0.25	0.27	0.25	0.35	0.64	0.27	0.25	0.27	0.47	3.77	0.25	0.27
E10 Equipment																									
E20 Furnishings																									
F10 Special Construction																									
F20 Selective Bldg Demolition																									
G10 Site Preparation																									
G20 Site Improvements																									
G30 Site Mechanical Utilities																									
G40 Site Electrical Utilities																									
G90 Other Site Construction																									
Total	7.58	28.71	2.08	1.61	2.99	3.33	1.84	2.82	1.62	2.85	3.14	29.10	1.87	1.66	2.23	7.78	1.86	4.44	1.62	8.73	1.70	18.02	5.13	1.61	2.22



Notes: A value of "0.00" means cost of more than \$0.00 but less than \$0.005 per gsft. All costs expressed in (\$) 2012 per gsft.

Year 1-25

Based on a 50-Year Forecast.

M&R Costs by System per Year Chart

Whitestone Research

04-Dec-13


Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

City: Washington, D.C.

Building Num: 1019/51/121

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	Total
A10 Foundations																											0.00
A20 Basement Construction																											0.00
B10 Super Structure			0.67										0.03						0.01				0.03				0.85
B20 Exterior Enclosure	0.05	7.28	0.05	0.06	0.05	0.05	7.75	0.05	0.05	0.05	0.05	0.09	0.05	0.06	0.05	0.05	9.23	0.05	0.05	0.05	0.05	0.06	0.14	0.05	0.05	0.05	57.10
B30 Roofing	0.32	0.30	0.22	0.22	0.22	4.33	4.95	0.22	0.22	0.22	0.26	0.30	0.22	0.22	0.22	0.32	1.45	0.22	0.22	0.22	0.26	0.30	0.22	0.22	0.22	0.22	29.24
C10 Interior Construction		0.01	0.00				0.24					0.00	0.01			0.00		0.07		0.00			0.01	0.00			0.61
C20 Stairs	0.04	0.02			0.04		0.06		0.04					0.04				0.66				0.04	0.02			0.04	3.48
C30 Interior Finishes		78.07			0.69				0.57		7.34			5.69			0.16		0.57		7.34			0.69		133.69	
D10 Conveying																											0.00
D20 Plumbing																											0.00
D30 HVAC	3.32	0.53	1.53	0.53	0.58	6.44	0.54	0.53	0.53	1.21	0.74	0.53	0.53	0.53	0.79	1.01	0.53	1.30	0.53	1.56	7.98	0.54	0.53	0.53	1.49	66.01	
D40 Fire Protection	0.57	0.55	1.88	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.55	2.97	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.55	0.57	35.08	
D50 Electrical	0.25	1.25	0.34	0.27	0.25	0.27	3.93	0.67	0.25	0.27	0.25	0.35	0.98	0.27	0.25	0.27	1.93	0.79	0.25	0.27	0.25	0.35	0.49	0.27	0.25	33.38	
E10 Equipment																											0.00
E20 Furnishings																											0.00
F10 Special Construction																											0.00
F20 Selective Bldg Demolition																											0.00
G10 Site Preparation																											0.00
G20 Site Improvements																											0.00
G30 Site Mechanical Utilities																											0.00
G40 Site Electrical Utilities																											0.00
G90 Other Site Construction																											0.00
Total	4.55	88.69	4.04	1.63	2.38	11.64	18.02	2.02	1.65	2.87	1.86	9.20	4.80	1.63	7.56	2.20	14.58	2.91	1.61	3.23	9.15	9.29	2.46	1.62	3.31	359.45	



Notes: A value of "0.00" means cost of more than \$0.00 but less than \$.005 per gsft. All costs expressed in (\$) 2012 per gsft.

Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
----------------	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---

B10 Super Structure

Repair Concrete Ramp (2% of Ramp)

109

Finish Repaired Concrete Ramp

4

Replace Concrete Ramp

Finish Replaced Concrete Ramp

Refinish Concrete Ramp

247

247

247

B20 Exterior Enclosure

Replace Aluminum Operable Window, 12 sf, 1st Floor

Replace Wood, Solid Core, Painted, Exterior Door

Repair Wood, Solid Core, Painted, Exterior Door

Replace Wood, Solid Core, Painted, Exterior Door Locks

Refinish Wood, Solid Core, Painted, Exterior Door

Maintain Wood, Solid Core, Painted, Exterior Door Locks

Replace Sliding, Motor-Operated, Exterior Door

Replace Sliding, Motor-Operated, Exterior Door Locks

Maintain Sliding, Motor-Operated, Exterior Door

Finish Replaced Wood, Solid Core, Painted, Exterior Door

Repair Aluminum Operable Window, 12 sf, 1st Floor

Replace Aluminum Fixed Window, 24 sf, 1st Floor

Repair Aluminum Fixed Window, 24 sf, 1st Floor

Repoint (50% surface) Concrete Block, Exterior, 1st Floor

Repair Concrete Block, Exterior, 1st Floor (2% of Walls)

Clean & Seal Concrete Block, Exterior, 1st Floor

Replace Aluminum Louver, 1st Floor

Refinish Aluminum Louver, 1st Floor

Maintain Sliding, Motor-Operated, Exterior Door Locks

541

957

78

71

15,458

44

442

27,540

27,540

1,636

1,636

152

152

35

35

35

35

B30 Roofing

Replace Membrane, Single-Ply Modified Bituminous/Thermopla

35,487

Replace Membrane, Single-Ply Roof w/ TPO Membrane

Minor Replacement, Single-Ply Roof w/ TPO (2% of Roof)

476

476

Non-Destructive Moisture Inspection

Maintain Single-Ply Roof w/ TPO Membrane

Non-Destructive Moisture Inspection

Maintain Single-Ply Modified Bituminous/Thermoplastic Roof

Replace Aluminum Gutter, Downspouts, Fittings

Maintain Aluminum Gutter, Downspouts, Fittings

322

322

322

322

322

322

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Based on a 50-Year Forecast.

Page 1, Year 1-25

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
----------------	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---

B10 Super Structure

Repair Concrete Ramp (2% of Ramp)																										
Finish Repaired Concrete Ramp																										
Replace Concrete Ramp							5,375																			
Finish Replaced Concrete Ramp							247																			
Refinish Concrete Ramp																	247									247

B20 Exterior Enclosure

Replace Aluminum Operable Window, 12 sf, 1st Floor																										
Replace Wood, Solid Core, Painted, Exterior Door																	3,766									
Repair Wood, Solid Core, Painted, Exterior Door																										
Replace Wood, Solid Core, Painted, Exterior Door Locks																										957
Refinish Wood, Solid Core, Painted, Exterior Door																	78									78
Maintain Wood, Solid Core, Painted, Exterior Door Locks																	71									71
Replace Sliding, Motor-Operated, Exterior Door																										15,458
Replace Sliding, Motor-Operated, Exterior Door Locks																	479									
Maintain Sliding, Motor-Operated, Exterior Door																	177									177
Finish Replaced Wood, Solid Core, Painted, Exterior Door																	78									
Repair Aluminum Operable Window, 12 sf, 1st Floor																										44
Replace Aluminum Fixed Window, 24 sf, 1st Floor																	10,559									
Repair Aluminum Fixed Window, 24 sf, 1st Floor																										442
Repoint (50% surface) Concrete Block, Exterior, 1st Floor																	43,834									
Repair Concrete Block, Exterior, 1st Floor (2% of Walls)																	4,647									
Clean & Seal Concrete Block, Exterior, 1st Floor																		27,540								27,540
Replace Aluminum Louver, 1st Floor																										
Refinish Aluminum Louver, 1st Floor																		152								152
Maintain Sliding, Motor-Operated, Exterior Door Locks																	35									35

B30 Roofing

Replace Membrane, Single-Ply Modified Bituminous/Thermopl																		35,487								
Replace Membrane, Single-Ply Roof w/ TPO Membrane																	34,801									
Minor Replacement, Single-Ply Roof w/ TPO (2% of Roof)																	476									476
Non-Destructive Moisture Inspection																	322									322
Maintain Single-Ply Roof w/ TPO Membrane																	277									277
Non-Destructive Moisture Inspection																	671									671
Maintain Single-Ply Modified Bituminous/Thermoplastic Roof																	531									531
Replace Aluminum Gutter, Downspouts, Fittings																	5,465									
Maintain Aluminum Gutter, Downspouts, Fittings																	287									287

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 1, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Repair Single-Ply Modified Bituminous/Thermoplastic Roof		9,599																							9,599

C10 Interior Construction

Replace Wood, Solid Core, Painted, Interior Door																									
Finish Replaced Wood, Solid Core, Painted, Interior Door																									
Replace Wood, Solid Core, Painted, Interior Door Locks		455																							455
Maintain Wood, Solid Core, Painted, Interior Door Locks		35					35																		35
Refinish Wood, Solid Core, Painted, Interior Door			39				39																		39

C20 Stairs

Finish Repaired Wood, Interior Railing																									4
Finish Replaced Wood, Painted Interior Stairs		235																							
Replace Wood, Painted, Interior Stairs			9,100																						
Finish Repaired Wood, Painted Interior Stairs																									7
Repair Wood, Painted, Interior Stairs																									154
Refinish Wood, Painted, Interior Stairs				235				235																	235
Finish Replaced Wood, Interior Railing		139																							
Replace Wood, Interior Railing		1,839																							
Refinish Metal, Painted, Exterior Railing		128																							128
Refinish Wood, Interior Railing				139				139																	139
Finish Replaced Metal, Painted, Exterior Railing																	109								
Replace Metal, Painted, Exterior Railing																	4,844								
Repair Concrete, Exterior Stairs																									126
Repair Metal, Painted, Exterior Railing																									
Replace Concrete, Exterior Stairs		1,630																							
Repair Wood, Interior Railing																									45
Finish Repaired Metal, Painted, Exterior Railing																									

C30 Interior Finishes

Finish Repaired Wood, Finished Ceiling		241																							241
Replace Wood Decking																									47,598
Refinish Concrete, Painted Flooring		6,683																							6,683
Repair Concrete, Painted Flooring (2% of Floors)																	1,202								
Finish Repaired Concrete, Painted Flooring																	133								
Replace Concrete, Painted Flooring																									
Finish Replaced Concrete, Painted Flooring																									
Repair Wood, Finished Ceiling (2% of Ceiling)		1,204															1,204								1,204
Replace Wood, Finished, Interior Paneling																									
Replace Wood, Finished Ceiling																									

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Based on a 50-Year Forecast.

Page 2, Year 1-25

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Repair Single-Ply Modified Bituminous/Thermoplastic Roof																									

C10 Interior Construction

Replace Wood, Solid Core, Painted, Interior Door																									
Finish Replaced Wood, Solid Core, Painted, Interior Door																									
Replace Wood, Solid Core, Painted, Interior Door Locks																									
Maintain Wood, Solid Core, Painted, Interior Door Locks		35																							
Refinish Wood, Solid Core, Painted, Interior Door			39																						

C20 Stairs

Finish Repaired Wood, Interior Railing																									
Finish Replaced Wood, Painted Interior Stairs																									
Replace Wood, Painted, Interior Stairs																									
Finish Repaired Wood, Painted Interior Stairs																									
Repair Wood, Painted, Interior Stairs																									
Refinish Wood, Painted, Interior Stairs		235				235					235					235						235			235
Finish Replaced Wood, Interior Railing																									
Replace Wood, Interior Railing																									
Refinish Metal, Painted, Exterior Railing																									
Refinish Wood, Interior Railing		139				139					139					139						139			139
Finish Replaced Metal, Painted, Exterior Railing																									
Replace Metal, Painted, Exterior Railing																									4,844
Repair Concrete, Exterior Stairs																									126
Repair Metal, Painted, Exterior Railing			170																						
Replace Concrete, Exterior Stairs																									
Repair Wood, Interior Railing																									45
Finish Repaired Metal, Painted, Exterior Railing			3																						

C30 Interior Finishes

Finish Repaired Wood, Finished Ceiling																	241								241	
Replace Wood Decking																		47,598								
Refinish Concrete, Painted Flooring																	6,683								6,683	
Repair Concrete, Painted Flooring (2% of Floors)																			1,202							
Finish Repaired Concrete, Painted Flooring																			133							
Replace Concrete, Painted Flooring		60,074																								
Finish Replaced Concrete, Painted Flooring		6,683																								
Repair Wood, Finished Ceiling (2% of Ceiling)																	1,204								1,204	
Replace Wood, Finished, Interior Paneling		403,542																								
Replace Wood, Finished Ceiling		60,175																								

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Based on a 50-Year Forecast.

Page 2, Year 26-50

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	
Finish Replaced Wood, Finished Ceiling													12,010														
Refinish Wood, Finished Ceiling																										12,010	
Finish Repaired Concrete Block, Painted, Interior Wall Finish																											
Refinish Concrete Block, Painted, Interior Wall Finish																											7,163
Refinish Wood Decking																											4,784
Repoint (50% surface) Concrete Block, Painted, Interior Wall Fi																											4,784
Repair Wood Decking (2% of Decking)																											950
Replace Concrete Block, Painted, Interior Wall Finish														77,864													
Finish Replaced Concrete Block, Painted, Interior Wall Finish														7,163													
Refinish Wood, Finished, Interior Paneling																											25,149
Repair Wood, Finished, Interior Paneling (2% of Walls)																											8,410
Finish Repaired Wood, Finished, Interior Paneling																											505
Finished Replaced Wood, Finished, Interior Paneling														25,149													
Repair Concrete Block, Painted, Interior Wall Finish (2% of Wal																											

D30 HVAC

Replace Pipe & Fittings, 1" Steel (20% of Pipe)																											523
Lubricate, Repack Gland, Ball Valve, 2"		423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	423	
Replace Ball Valve, 2"																											2,498
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel																											
Replace Existing Ductwork (20% of Ductwork)																											5,403
Replace 10' Section, Pipe & Fittings, 1" Steel																											26
Replace Thermostat														1,090													1,090
Maintain Thermostat														80	80	80	80	80	80	80	80	80	80	80	80	80	80
Replace HVAC Control Panel																											4,927
Minor Repair, HVAC Control Panel														352													352
Inspect & Maintain HVAC Control Panel														97	97	97	97	97	97	97	97	97	97	97	97	97	97
Replace Secondary Coil, 24" x 36"																											3,587
Replace Steel Damper, Motorized																											
Refinish Steel Damper, Motorized																											170
Clean, Lubricate, and Inspect Steel Damper, Motorized																											83
Replace Exhaust Fan, Centrifugal, 16,000 Cfm														12,421													12,421
Maintain Exhaust Fan, Centrifugal, 16,000 Cfm														290	290	290	290	290	290	290	290	290	290	290	290	290	290
Replace Duct Insulation (20% of Insulation)																											2,252
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel																											
Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam																											38
Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20																											174
Maintain Flow Control Valve & Actuator, 2"														592	592	592	592	592	592	592	592	592	592	592	592	592	592

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 3, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

	Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Batteries & Check Operation, Smoke Detector, Duct		62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	
Repair Smoke Detector																										397
Repair Smoke Detector, Duct																										160
Replace Smoke Detector																										1,176
Replace Smoke Detector, Duct																										1,563
Maintain & Repair General Wiring, Lightning Protection System	74		74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	
Maintain Disconnect Switch, 60 Amp.	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ Ba	106																									106
Replace Fire Alarm Bell, 6"																										590
Maintain Power Panel Board, 208 Y/120 V, 225 Amp.	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	
Maintain Disconnect Switch, 30 Amp.	39		39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	
Repair Disconnect Switch, 30 Amp.																										247
Replace Disconnect Switch, 30 Amp.																										581
Replace Lightning Protection General Wiring																										7,611
Repair Disconnect Switch, 60 Amp.																										251
Maintain Disconnect Switch, 100 Amp.	223	112	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	
Repair Disconnect Switch, 100 Amp.																										286
Replace Disconnect Switch, 100 Amp.																										1,971
Maintain Power Panel Board, 208 Y/120 V, 100 Amp.	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	
Replace Disconnect Switch, 60 Amp.																										1,037
Replace Power Panel Board, 208 Y/120 V, 100 Amp.																										6,125
Replace Compact Fluorescent Lighting Fixture, 32 w																										1,037
Repair Power Panel Board, 208 Y/120 V, 225 Amp.																										189
Replace Power Panel Board, 208 Y/120 V, 225 Amp.																										9,250
Maintain Power Panel Board, 480 V, 200 Amp.	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	
Repair Power Panel Board, 480 V, 200 Amp.																										189
Replace Power Panel Board, 480 V, 200 Amp.																										11,786
Maintain Secondary Transformer, Dry, 30 kVA	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	
Repair Secondary Transformer, Dry, 30 kVA																										436
Replace Secondary Transformer, Dry, 30 kVA																										7,104
Replace Ballast & Lamps, Compact Fluorescent Lighting Fixture,																										902
Repair Power Panel Board, 208 Y/120 V, 100 Amp.																										189

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Attitude Control Lab Bldg/MTS

Facility: Goddard Space Flight Center

Building Num: 1019/51/121

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2		
Replace Batteries & Check Operation, Smoke Detector, Duct	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62			
Repair Smoke Detector											397														397		
Repair Smoke Detector, Duct											160														160		
Replace Smoke Detector																										1,176	
Replace Smoke Detector, Duct																										1,563	
Maintain & Repair General Wiring, Lightning Protection System	74		74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74		
Maintain Disconnect Switch, 60 Amp.	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/	106		106		106		106		106		106		106		106		106		106		106		106		106		106
Replace Fire Alarm Bell, 6"			590																							590	
Maintain Power Panel Board, 208 Y/120 V, 225 Amp.	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120		
Maintain Disconnect Switch, 30 Amp.	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	39	
Repair Disconnect Switch, 30 Amp.											247														247		
Replace Disconnect Switch, 30 Amp.																											
Replace Lightning Protection General Wiring			7,611																								
Repair Disconnect Switch, 60 Amp.											251																
Maintain Disconnect Switch, 100 Amp.	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223	223		
Repair Disconnect Switch, 100 Amp.											286	286									286	286					
Replace Disconnect Switch, 100 Amp.																											
Maintain Power Panel Board, 208 Y/120 V, 100 Amp.	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120		
Replace Disconnect Switch, 60 Amp.																							1,163				
Replace Power Panel Board, 208 Y/120 V, 100 Amp.																							6,125				
Replace Compact Fluorescent Lighting Fixture, 32 w																							1,037				
Repair Power Panel Board, 208 Y/120 V, 225 Amp.											189											189					
Replace Power Panel Board, 208 Y/120 V, 225 Amp.																											
Maintain Power Panel Board, 480 V, 200 Amp.	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120		
Repair Power Panel Board, 480 V, 200 Amp.											189											189					
Replace Power Panel Board, 480 V, 200 Amp.																											
Maintain Secondary Transformer, Dry, 30 kVA	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120	120		
Repair Secondary Transformer, Dry, 30 kVA											436																
Replace Secondary Transformer, Dry, 30 kVA																						7,104					
Replace Ballast & Lamps, Compact Fluorescent Lighting Fixtur											902																
Repair Power Panel Board, 208 Y/120 V, 100 Amp.											189																

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

Based on a 50-Year Forecast.

All costs expressed in (\$) 2012.

Page 5, Year 26-50

Operation Costs Summary

Whitestone Research

Building: B-Attitude Control Lab Bldg/MTS

GSFT: 8,360

Building Number: 1019/51/121

Replacement Value: \$10,712,733

Facility: Goddard Space Flight Center


Building Use: Laboratory

City: Washington, D.C.

Building Type: Space Science Building

Built Date: 1964

Operation	Annual Cost/GSFT	Annual Total	Percent
Custodial	\$2.153	\$18,001	12.0%
Energy	\$1.358	\$11,350	7.6%
Grounds	\$0.126	\$1,051	0.7%
M&R	\$7.189	\$60,099	40.1%
Management	\$3.204	\$26,782	17.9%
Pest Control	\$0.059	\$490	0.3%
Refuse	\$0.033	\$275	0.2%
Road Clearance	\$0.015	\$129	0.1%
Security	\$3.354	\$28,037	18.7%
Telecom	\$0.108	\$900	0.6%
Water/Sewer	\$0.335	\$2,804	1.9%
Building Total	\$17.93	\$149,919	100.0%



Building Operations Task Details

Whitestone Research

Building: B-Attitude Control Lab Bldg/MTS

Year Built: 1964

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/121

City: Washington, D.C.

Replacement Value: \$10,712,733

per SF: \$1,281

Building Gsft: 8,360

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Custodial		Level of Service: Medium			
Laboratory	6688	Wet Mop & Rinse Hard Floor with 32 oz. Mop Using Single Bucket & Wringer	\$8,655	\$1,406	\$10,061
Laboratory	6688	Empty Trash; Wipe Clean & Re-line Basket	\$1,442	\$234	\$1,677
Laboratory	6688	Clean and Wipe Furniture with Trigger Sprayer & Cloth	\$1,279	\$208	\$1,487
Laboratory	6688	Dust Surfaces with Duster	\$962	\$156	\$1,118
Laboratory	6688	Dust Window Blinds	\$462	\$75	\$537
Office	836	Vacuum Carpet with 14" Upright Vacuum	\$1,262	\$205	\$1,467
Office	836	Empty Trash; Wipe Clean & Re-line Basket	\$180	\$29	\$210
Office	836	Clean and Wipe Furniture with Trigger Sprayer & Cloth	\$160	\$26	\$186
Office	836	Dust Surfaces with Duster	\$120	\$20	\$140
Office	836	Vacuum Upholstered Furniture with Tank or Canister Vacuum	\$62	\$10	\$72
Office	836	Dust Window Blinds	\$58	\$9	\$67
Common/Circulation Are	418	Vacuum Carpet with 14" Upright Vacuum	\$631	\$103	\$734
Common/Circulation Are	418	Vacuum Upholstered Furniture with Tank or Canister Vacuum	\$92	\$15	\$107
Common/Circulation Are	418	Empty Trash; Wipe Clean & Re-line Basket	\$90	\$15	\$105
Mechanical/Equipment R	418	Sweep Hard Floor with 48" Push Broom	\$16	\$3	\$19
Mechanical/Equipment R	418	Empty Trash; Wipe Clean & Re-line Basket	\$14	\$2	\$16
Total:			\$15,485	\$2,516	\$18,001
Operation: Grounds		Level of Service: Low			
Grounds, Improved	5016	Mow Turfgrass with 21" Power Mower	\$190	\$79	\$269
Grounds, Improved	5016	Aerate Improved Grounds	\$142	\$59	\$201
Grounds, Improved	5016	Clear Shrubs	\$119	\$49	\$168
Grounds, Improved	5016	Edge Clean & Trim Walks with Gas Powered Edger	\$79	\$33	\$112
Grounds, Improved	5016	Overseed, Improved Grounds	\$71	\$30	\$101
Grounds, Improved	5016	Vacuum with 30" Billy Goat	\$47	\$20	\$67
Grounds, Improved	5016	Clear Crabgrass	\$36	\$15	\$50
Grounds, Improved	5016	Clear Weeds with 15" Boom, Improved Grounds	\$19	\$8	\$27
Grounds, Improved	5016	Trim Around Raised Objects with String Edger	\$16	\$7	\$23

All costs expressed in (\$) 2012.

04-Dec-13

Page 1

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Grounds, Improved	5016	Fertilize Improved Grounds	\$14	\$6	\$20
Grounds, Improved	5016	Sweep with 30" Power Rake	\$9	\$4	\$13
Grounds, Improved	5016	Fertilize Using Power Take Off Broadcast	\$0	\$0	\$0
Total:			\$742	\$309	\$1,051
Operation: Pest Control	Level of Service: Low				
Pest Controlled	8360	Install, or Check and Re-Bait 5 Rodent Boxes	\$131	\$55	\$186
Pest Controlled	8360	Inspect Building for Pests	\$164	\$0	\$164
Pest Controlled	8360	Perform Crawling Insect Abatement	\$99	\$41	\$140
Total:			\$394	\$96	\$490
Operation: Road Clearance	Level of Service: Medium				
Pavement NASA	6688	Plow Paved Area	\$99	\$30	\$129
Total:			\$99	\$30	\$129
Operation: Security	Level of Service: High				
Secured Area	8360	Guard Lobby/Parking	\$12,286	\$1,997	\$14,283
Secured Area	8360	Patrol Building Perimeter	\$2,119	\$344	\$2,464
Total:			\$14,406	\$2,341	\$16,746

Building Operations Utility Details

Whitestone Research

Building: B-Attitude Control Lab Bldg/MTS

Year Built: 1964

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/121

City: Washington, D.C.

Replacement Value: \$10,712,733

per SF: \$1,281

Building Gsft: 8,360

	Utility	GSFT	Demand	UM	Rate	Cost
Operation: Energy	Level of Service: Low					
	Electricity	8360	13.020	kWh	\$0.0820	\$8,925
	Natural Gas	8360	0.558	Thm	\$0.5200	\$2,425
	Diesel	8360	0.000	Gal	\$3.3400	\$0
	Total:		13.578			\$11,350
Operation: Refuse	Level of Service: Medium					
	Municipal Solid Waste	8360	0.370	Lbs	\$0.0711	\$220
	Recycling	8360	0.180	Lbs	\$0.0367	\$55
	Total:		0.550			\$275
Operation: Water/Sewer	Level of Service: Medium					
	Sewer	8360	18.920	Gal	\$0.0092	\$1,455
	Water	8360	24.080	Gal	\$0.0067	\$1,349
	Total:		43.000			\$2,804

Building Operations Management Details

Whitestone Research

Building: B-Attitude Control Lab Bldg/MTS

Year Built: 1964

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/121

City: Washington, D.C.

Replacement Value: \$10,712,733 **per SF:** \$1,281

Building Gsft: 8,360

	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$10,712,733	\$26,782
	Total:				\$26,782

Building Operations Service Details

Whitestone Research

Building: B-Attitude Control Lab Bldg/MTS	Year Built: 1964	FTEs: 1	Building Type: Space Science Building
Facility: Goddard Space Flight Center	Original Cost: \$1		Building Num: 1019/51/121
City: Washington, D.C.	Replacement Value: \$10,712,733	per SF: \$1,281	Building Gsft: 8,360

Service*	Quantity	Rate	Cost
Operation: Security Level of Service: High			
Intrusion Detection Systems	1	\$4,986	\$4,986
System Monitoring	1	\$3,615	\$3,615
Access Control	1	\$2,690	\$2,690
Total:			\$11,291
Operation: Telecom Level of Service: High			
Local Telephone	1	\$468	\$468
Data	1	\$3,588	\$240
Long Distance Telephone	1	\$192	\$192
Total:			\$900

**Attachment B: Detailed MARS Reports for GSFC Property ID
1019/51/50**

Building Component List

Whitestone Research

Building: B-Central Flight Control/Range Bldg

Year Built: 1961

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/50

City: Washington, D.C.

Replacement Value: \$41,722,280 **per SF:** \$366

Building Gsft: 113,961

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
B1010		Concrete Decking	1961	1200 Sq Ft	Loading Dock	
B2010		Aluminum Curtain Wall System	1992	3040 Sq Ft		
B2010		Aluminum Curtain Wall System	1980	2550 Sq Ft		
B2010		Aluminum Siding, Exterior, 3rd+ Floor	1961	3810 Sq Ft		
B2010		Clay Brick, Exterior, 1st Floor	1961	12995 Sq Ft		
B2010		Clay Brick, Exterior, 2nd Floor	1961	4980 Sq Ft		
B2010		Clay Brick, Exterior, 3rd+ Floor	1961	1150 Sq Ft		
B2010		Concrete Cast-in-place, Painted, Exterior, 1st Floor	1961	1500 Sq Ft		
B2010		Concrete Cast-in-place, Painted, Exterior, 2nd Floor	1961	1000 Sq Ft		
B2030		Aluminum Frame, Fully Glazed, Exterior Door	1961	5 Each		
B2030		Steel, Painted, Exterior Door	1961	1 Each		
B2030		Steel, Painted, Exterior Double Door	1961	3 Each		
B3010		Built-up Roof	1995	18320 Sq Ft		
B3010		Built-up Roof w/ Cool Reflective Coating	1995	15322 Sq Ft		
B3010		Metal Awning	1995	1250 Sq Ft		
B3010		Metal Roof	1995	1700 Sq Ft		
C1010		Toilet Partitions, Painted Metal, Overhead Braced	1995	16 Each		
C1010		Toilet Partitions, Painted Metal, Overhead Braced	2000	16 Each		
C1020		Aluminum, Fully Glazed, Interior Door	1961	7 Each		
C1020		Steel, Painted, Interior Door	1961	79 Each		
C1020		Steel, Painted, Interior Door	2011	10 Each		
C1020		Steel, Painted, Interior Double Door	1961	27 Each		
C1020		Steel, Painted, Interior Double Door w/ Safety Glass	1961	10 Each		
C1020		Steel, Painted, w/ Safety Glass, Interior Door	1961	3 Each		
C1020		Wood, Solid Core w/ Safety Glass, Painted, Interior Door	2000	34 Each		
C1020		Wood, Solid Core w/ Safety Glass, Painted, Interior Door	1961	21 Each		
C1020		Wood, Solid Core w/ Safety Glass, Painted, Interior Door	2010	12 Each		
C1020		Wood, Solid Core, Painted, Interior Door	1961	67 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

04-Dec-13

All costs expressed in (\$) 2012.

Page 1

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
C1020		Wood, Solid Core, Painted, Interior Door	2000	6 Each		
C2010		Concrete, Exterior Stairs	1961	75 Sq Ft		
C2010		Concrete, Interior Stairs	1961	1150 Sq Ft		
C2010		Metal, Painted, Exterior Railing	1961	65 Ln Ft		
C2010		Wood, Interior Railing	1961	480 Ln Ft		
C3010		Ceramic Tile, 4"x4", Interior Wall Finish	1990	855 Sq Ft		
C3010		Ceramic Tile, 4"x4", Interior Wall Finish	1961	250 Sq Ft		
C3010		Ceramic Tile, 4"x4", Interior Wall Finish	1995	1620 Sq Ft		
C3010		Clay Brick, Painted, Interior Wall Finish	1961	10380 Sq Ft		
C3010		Concrete Block, Painted, Interior Wall Finish	1961	15000 Sq Ft		
C3010		Concrete, Painted, Interior Wall Finish	1961	5500 Sq Ft		
C3010		Fabric, Interior Wall Finish	1985	2410 Sq Ft		
C3010		Fabric, Interior Wall Finish	1990	915 Sq Ft		
C3010		Fabric, Interior Wall Finish	1995	6075 Sq Ft		
C3010		Fabric, Interior Wall Finish	2011	1680 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	1961	250 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	1975	5650 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	1985	17550 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	1990	22450 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	1995	6405 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	2000	8065 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	2011	2500 Sq Ft		
C3010		Gypsum Board, Interior Wall Finish	1992	4545 Sq Ft		
C3010		Plaster, Interior Wall Finish	2012	90 Sq Ft		
C3010		Plaster, Interior Wall Finish	2000	220 Sq Ft		
C3010		Plate Glass Interior Wall	1961	110 Sq Ft		
C3010		Wallpaper, Interior Wall Finish	1999	2500 Sq Ft		
C3010		Wood, Finished, Interior Paneling	1995	580 Sq Ft		
C3010		Wood, Finished, Interior Paneling	2005	1240 Sq Ft		
C3020		Access Flooring w/ Carpet, Raised	2002	3774 Sq Ft		
C3020		Access Flooring w/ Carpet, Raised	2007	3800 Sq Ft		
C3020		Access Flooring w/ Carpet, Raised	2011	2500 Sq Ft		
C3020		Access Flooring w/ Laminate, Raised	2011	3739 Sq Ft		
C3020		Access Flooring w/ Laminate, Raised	1985	9741 Sq Ft		
C3020		Access Flooring w/ Laminate, Raised	1995	4224 Sq Ft		
C3020		Access Flooring w/ Laminate, Raised	1992	16551 Sq Ft		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
C3020		Carpet, Nylon 20 oz., Low Traffic	2002	10471 Sq Ft		
C3020		Carpet, Nylon 20 oz., Low Traffic	2007	6561 Sq Ft		
C3020		Carpet, Nylon 20 oz., Low Traffic	2011	1325 Sq Ft		
C3020		Ceramic Tile Flooring	1961	1200 Sq Ft		
C3020		Concrete Flooring	1961	1845 Sq Ft		
C3020		Concrete, Painted Flooring	1961	7500 Sq Ft		
C3020		Rubber Tile Flooring	2002	475 Sq Ft		
C3020		Terrazzo Flooring	1961	3600 Sq Ft		
C3020		Vinyl Tile Flooring	1961	12675 Sq Ft		
C3020		Vinyl Tile Flooring	2002	1950 Sq Ft		
C3020		Vinyl Tile Flooring	1980	10475 Sq Ft		
C3020		Vinyl Tile Flooring	1992	11555 Sq Ft		
C3030		Acoustical Tile, Dropped Ceiling	1975	16364 Sq Ft		
C3030		Acoustical Tile, Dropped Ceiling	1985	21005 Sq Ft		
C3030		Acoustical Tile, Dropped Ceiling	1990	16555 Sq Ft		
C3030		Acoustical Tile, Dropped Ceiling	1995	18500 Sq Ft		
C3030		Acoustical Tile, Dropped Ceiling	2002	6343 Sq Ft		
C3030		Acoustical Tile, Dropped Ceiling	2012	2430 Sq Ft		
C3030		Concrete, Painted Ceiling	1961	4615 Sq Ft		
C3030		Metal, Painted Ceiling	1961	6500 Sq Ft		
C3030		Metal, Painted Ceiling	1985	6500 Sq Ft		
D1010		Elevator, Hydraulic, 2,500 lbs, 3-5 Floor, 200 fpm	1995	1 Each		
D1010		Wheel Chair Lift	1995	1 Each		
D2010		Drinking Fountain, Refrigerated	1990	2 Each		
D2010		Drinking Fountain, Refrigerated	2000	13 Each		
D2010		Emergency Eye Wash	2000	1 Each		
D2010		Lavatory, Vitreous China	1995	10 Each		
D2010		Lavatory, Vitreous China	2000	18 Each		
D2010		Service Sink, Floor	2000	1 Each		
D2010		Service Sink, Floor	2000	1 Each		
D2010		Sink, Plastic	1990	1 Each		
D2010		Sink, Stainless Steel	1990	1 Each		
D2010		Sink, Stainless Steel	1995	1 Each		
D2010		Sink, Stainless Steel	2000	4 Each		
D2010		Tankless Water Closet	1995	12 Each		
D2010		Tankless Water Closet	2000	16 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
D2010		Urinal, Vitreous China	1995	4 Each		
D2010		Urinal, Vitreous China	2000	13 Each		
D2020		Circulator Pump, 1/2 HP, Cold Water	1995	3 Each		
D2020		Circulator Pump, 1/2 HP, Hot Water	2008	1 Each		
D2020		Pipe & Fittings, 1" Steel	1990	0.7 K Ln Ft		
D2020		Pipe & Fittings, 2" Copper, Cold Water	1990	0.7 K Ln Ft		
D2020		Pipe & Fittings, 3/4" Copper, Cold Water	1990	1.1 K Ln Ft		
D2020		Pipe & Fittings, 3/4" Copper, Cold Water	1961	0.2 K Ln Ft		
D2020		Pipe & Fittings, 3/4" Copper, Hot Water	1990	0.9 K Ln Ft		
D2020		Pipe & Fittings, 3/4" Copper, Hot Water	1961	0.2 K Ln Ft		
D2020		Pipe & Fittings, 4" Copper, Cold Water	1992	0.8 K Ln Ft		
D2020		Pipe Insulation, Fiberglass, Cold Water	1992	0.8 K Ln Ft		
D2020		Pipe Insulation, Fiberglass, Hot Water	1992	1 K Ln Ft		
D2020		Water Heater, Gas/Oil, 30 Gph	2008	1 Each		
D2030		Backflow Preventer, 2"	2000	1 Each		
D2030		Backflow Preventer, 3/4"	2000	3 Each		
D2030		Floor Drain	1961	9 Each		
D2030		Pipe & Fittings, 10" Cast Iron	1961	0.4 K Ln Ft		
D2030		Pipe & Fittings, 2" PVC	1992	0.7 K Ln Ft		
D2030		Pipe & Fittings, 3" Cast Iron	1985	0.9 K Ln Ft		
D2030		Pipe & Fittings, 4" Cast Iron	2011	0.1 K Ln Ft		
D2030		Pipe & Fittings, 4" PVC	1995	0.2 K Ln Ft		
D2030		Pipe & Fittings, 6" Cast Iron	1970	0.5 K Ln Ft		
D2030		Pipe & Fittings, 6" Cast Iron	1961	0.2 K Ln Ft		
D2030		Pipe & Fittings, 6" Cast Iron	1992	0.2 K Ln Ft		
D2030		Sewage Ejector Pump, 1 HP	1995	1 Each		
D2040		Roof Drain, 4-6"	1961	22 Each		
D2040		Sump Pump, 1 HP	1995	6 Each		
D2040		Sump Pump, 3 HP	1990	2 Each		
D2090		Air Compressor, 10 HP	1990	1 Each		
D2090		Air Compressor, 2 HP	2007	1 Each		
D3010		Leak Detection, Panel & Float Assembly	1995	1 Each		
D3020		Ball Valve, 6"	1996	8 Each		
D3020		Condensate Receiver Station, 10-15 Gal.	2000	2 Each		
D3020		Expansion Tank, 10 Gal.	1990	2 Each		
D3020		Expansion Tank, 100 Gal.	1961	2 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Page 4

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
D3020		Flash Tank, 24 Gal.	1995	1 Each		
D3020	HWC-001	Heat Exchanger, Steam-to-Water, 25 Gpm	1997	1 Each		
D3020		Pipe & Fittings, 1" Steel	1992	1.1 K Ln Ft		
D3020		Pipe & Fittings, 1" Steel	1974	0.4 K Ln Ft		
D3020		Pipe & Fittings, 1" Steel	2011	0.05 K Ln Ft		
D3020		Pipe & Fittings, 2" Steel	2011	0.3 K Ln Ft		
D3020		Pipe & Fittings, 2" Steel	1974	0.25 K Ln Ft		
D3020		Pipe & Fittings, 2" Steel	1992	1.2 K Ln Ft		
D3020		Pipe & Fittings, 3" Steel	1990	0.4 K Ln Ft		
D3020		Pipe & Fittings, 3/4" Copper	2001	0.2 K Ln Ft		
D3020		Pipe & Fittings, 3/4" Copper	1992	1.4 K Ln Ft		
D3020		Pipe & Fittings, 4" Steel	1992	0.4 K Ln Ft		
D3020		Pipe & Fittings, 6" Steel	1992	0.4 K Ln Ft		
D3020		Pipe & Fittings, 6" Steel	1974	0.2 K Ln Ft		
D3020		Pipe Insulation, Fiberglass, Heating Water/Steam	1974	0.9 K Ln Ft		
D3020		Pipe Insulation, Fiberglass, Heating Water/Steam	2011	0.8 K Ln Ft		
D3020		Pipe Insulation, Fiberglass, Heating Water/Steam	1992	2.2 K Ln Ft		
D3030		Ball Valve, 4"	1990	4 Each		
D3030		Butterfly Valve, 4"	1990	4 Each		
D3030		Circulation Pump, 2 HP, Chiller & Condenser Water	1990	1 Each		
D3030		Circulation Pump, 2 HP, Chiller & Condenser Water	1990	2 Each		
D3030		Circulation Pump, 2 HP, Chiller & Condenser Water	2007	1 Each		
D3030	CHP-020	Circulation Pump, 2 HP, Chiller & Condenser Water	1992	1 Each		
D3030		Circulation Pump, 5 HP, Chiller & Condenser Water	1990	1 Each		
D3030	CHP-019A, B	Circulation Pump, 7 1/2 HP, Chiller & Condenser Water	1995	2 Each		
D3030		Circulation Pump, 7 1/2 HP, Chiller & Condenser Water	1990	1 Each		
D3030		Circulator Pump, 1/6 HP, Chilled Water	2000	2 Each		Cond.
D3030		Condenser, Air Cooled, 2 Ton	2012	1 Each		
D3030		Condenser, Air Cooled, 5 Ton	1995	5 Each		
D3030		Flow Control Valve, Motorized, 6"	1990	6 Each		
D3030		Pipe & Fittings, 1" Copper	1992	1 K Ln Ft		
D3030		Pipe & Fittings, 1" Copper	2010	0.25 K Ln Ft		
D3030		Pipe & Fittings, 1" Steel	2010	0.25 K Ln Ft		
D3030		Pipe & Fittings, 1" Steel	1992	1.4 K Ln Ft		
D3030		Pipe & Fittings, 2" Steel	2007	6 K Ln Ft		
D3030		Pipe & Fittings, 2" Steel	1974	0.4 K Ln Ft		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
D3030		Pipe & Fittings, 2" Steel	1992	1.4 K Ln Ft		
D3030		Pipe & Fittings, 3" Steel	1992	0.25 K Ln Ft		
D3030		Pipe & Fittings, 4" Steel	2010	0.1 K Ln Ft		
D3030		Pipe Insulation, Fiberglass, Chilled Water	1992	4.2 K Ln Ft		
D3030		Pipe Insulation, Fiberglass, Chilled Water	1961	0.3 K Ln Ft		
D3030		Pipe Insulation, Fiberglass, Chilled Water	1974	0.3 K Ln Ft		
D3030		Pipe Insulation, Fiberglass, Chilled Water	2010	0.8 K Ln Ft		
D3040		Air Curtain, 1,000 Cfm	1995	1 Each		
D3040	ACS-003	Air Handler, Multizone, 10,000 Cfm	1961	1 Each		
D3040	ACS-002,004	Air Handler, Multizone, 15,000 Cfm	1961	2 Each		
D3040	ACS-005	Air Handler, Multizone, 20,000 Cfm	1961	1 Each		
D3040	ACS-20, 19	Air Handler, Multizone, 20,000 Cfm	1992	2 Each		
D3040	ACS-001	Air Handler, Multizone, 50,000 Cfm	1961	1 Each		
D3040	ACS-23	Air Handler, Multizone, 8,000 Cfm	1995	1 Each		
D3040	AHU-042	Air Handler, Single Zone, 1,300 Cfm	1992	1 Each		
D3040	ACS-22	Air Handler, Single Zone, 10,000 Cfm	2007	1 Each		
D3040	ACS-21, 24	Air Handler, Single Zone, 10,000 Cfm	2000	2 Each		
D3040	AHU-014	Air Handler, Single Zone, 2,500 Cfm	1992	1 Each		
D3040	ACS-008	Air Handler, Single Zone, 20,000 Cfm	1961	1 Each		
D3040		Duct Insulation, Fiberglass Blanket	2010	2000 Sq Ft		
D3040		Duct Insulation, Fiberglass Blanket	1974	6000 Sq Ft		
D3040		Duct Insulation, Fiberglass Blanket	1992	26500 Sq Ft		
D3040		Ductwork	2011	3400 Lbs		
D3040		Ductwork	1992	66000 Lbs		
D3040		Ductwork	1974	14000 Lbs		
D3040		Exhaust Fan, Ceiling, 200-500 Cfm	1995	4 Each		
D3040		Exhaust Fan, Ceiling, 200-500 Cfm	2000	1 Each		
D3040	RAF-001, 002	Exhaust Fan, Centrifugal, 10,000 Cfm	1961	2 Each		
D3040	EXH-11, 12, 13	Exhaust Fan, Centrifugal, 2,000 Cfm	1961	3 Each		
D3040	RAF-003, 004	Exhaust Fan, Centrifugal, 2,000 Cfm	1961	2 Each		
D3040	EXH-022, 025, 026	Exhaust Fan, Centrifugal, 2,000 Cfm	1995	3 Each		
D3040	EF-2	Exhaust Fan, Centrifugal, 2,000 Cfm	1961	1 Each		
D3040	EXH-006	Exhaust Fan, Centrifugal, 2,000 Cfm	1995	1 Each		
D3040	RAF-005, 023	Exhaust Fan, Centrifugal, 5,000 Cfm	1995	2 Each		
D3040		Exhaust Fan, Roof Mounted, 2,000 Cfm	1990	2 Each		
D3040		Exhaust Fan, Roof Mounted, 2,000 Cfm	2000	2 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
D3040		Variable Air Volume Box, 800 Cfm	2000	4 Each		
D3050	ACS-25,26,27,28	Air Conditioner, Computer Room, Air Cooled, 10 Ton	1995	4 Each		
D3050	ACS-29	Air Conditioner, Computer Room, Air Cooled, 3 Ton	2000	1 Each		
D3050	AHU-47,48,49	Air Conditioner, Computer Room, Air-Cooled, 2 Ton	2009	3 Each		
D3050	ACU-45, 021, 037, 41, 4	Air Conditioner, Computer Room, Chilled Water, 10 Ton	1995	5 Each		
D3050	ACS-36, 44	Air Conditioner, Computer Room, Chilled Water, 15 Ton	1994	2 Each		
D3050	ACS-45	Air Conditioner, Computer Room, Chilled Water, 5 Ton	2008	1 Each		
D3050	AHU-50	Air Conditioner, DX Packaged, Air Cooled, 2 Ton	2012	1 Each		
D3050	WCC-001	Air Conditioner, DX Packaged, Air Cooled, 5 Ton	2009	1 Each		
D3050		Fan Coil Unit, 1 Ton	2000	65 Each	Offices	
D3050		Fan Coil Unit, 1 Ton	1992	4 Each	Stairs	
D3050	AHU-030, 031	Fan Coil Unit, 1 Ton	2000	2 Each		
D3050		Fan Coil Unit, 2 Ton	2000	3 Each		
D3050	ACS-39	Fan Coil Unit, 2 Ton	2000	1 Each		
D3050	ACS-107, 207, 307	Fan Coil Unit, 2 Ton	1997	3 Each		
D3050		Unit Heater, 480v, 5kW	2000	1 Each		
D3060		Direct Digital Controls, System Points	1999	370 Each		
D3060		HVAC Control Panel	1961	2 Each		
D3060		HVAC Control Panel	1961	4 Each		
D3060		Thermostat	1961	25 Each		
D3060		Thermostat	2000	30 Each		
D3070		Air Sample Smoke Detection System	2000	5 Each		
D4010		Fire Alarm Control Panel	2000	1 Each		
D4010		Fire Department Connection, Siamese, 3"	2000	3 Each		
D4010		Fire Department Connection, Siamese, 3"	2000	5 Each		
D4010		Fire Sprinkler Head	1980	227 Each		
D4010		Fire Sprinkler Head	1992	260 Each		
D4010		Fire Sprinkler Head	2000	164 Each		
D4010		Fire Sprinkler System	2000	1 Each		
D4010		Gate Valve, 4"	1995	5 Each		
D4010		Gate Valve, 4"	2000	2 Each		
D4010		Pipe & Fittings, 1" Steel	1980	0.35 K Ln Ft		
D4010		Pipe & Fittings, 1" Steel	1980	0.55 K Ln Ft		
D4010		Pipe & Fittings, 2" Steel	1980	0.265 K Ln Ft		
D4010		Pipe & Fittings, 2" Steel	1992	0.5 K Ln Ft		
D4010		Pipe & Fittings, 4" Steel	1980	0.175 K Ln Ft		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
D4010		Pipe & Fittings, 4" Steel	1992	0.25 K Ln Ft		
D4010		Valves & Components, Sprinkler System, 3"	2000	1 Each		
D5010		Bus Duct & Fittings, AL, 800-4,000 Amp.	1961	150 Ln Ft		
D5010		Bus Duct & Fittings, AL, 800-4,000 Amp.	1992	250 Ln Ft		
D5010		Bus Switch, 60 Amp.	1961	5 Each		
D5010		Bus Switch, 60 Amp.	1992	10 Each		
D5010		Circuit Breaker, 600 V, 30-60 Amp., 3Ph.	1997	1 Each		
D5010		Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.	1997	2 Each		
D5010		Disconnect Switch, 100 Amp.	2005	2 Each		
D5010		Disconnect Switch, 100 Amp.	1995	1 Each		
D5010		Disconnect Switch, 100 Amp.	1985	2 Each		
D5010		Disconnect Switch, 30 Amp.	1995	3 Each		
D5010		Disconnect Switch, 30 Amp.	2000	4 Each		
D5010		Disconnect Switch, 30 Amp.	1961	1 Each		
D5010		Disconnect Switch, 30 Amp.	2012	1 Each		
D5010		Disconnect Switch, 30 Amp.	2008	4 Each		
D5010		Disconnect Switch, 30 Amp.	1990	6 Each		
D5010		Disconnect Switch, 30 Amp.	2010	1 Each		
D5010		Disconnect Switch, 60 Amp.	2005	1 Each		
D5010		Disconnect Switch, 60 Amp.	1990	1 Each		
D5010		Disconnect Switch, 60 Amp.	2000	1 Each		
D5010		Load Bank, Indoor	1997	5 Each		
D5010		Main Switchgear, 480 V, 2,000 Amp.	2005	2 Each		
D5010		Motor Control Center w/ Main Breaker, 480 V, 600 Amp.	1997	1 Each		7 SECTIONS
D5010		Motor Control Center w/ Main Breaker, 480 V, 600 Amp.	1997	1 Each		1 SECTION
D5010		Motor Control Center w/ Main Breaker, 480 V, 600 Amp.	1997	1 Each		6 SECTIONS
D5010		Motor Control Center w/ Main Breaker, 480 V, 600 Amp.	2005	2 Each		
D5010		Motor Starter, 5-20 HP, <600 V	2005	1 Each		
D5010		Motor Starter, 5-20 HP, <600 V	1995	3 Each		
D5010		Motor Starter, 5-20 HP, <600 V	1961	1 Each		
D5010		Motor Starter, 5-20 HP, <600 V	1997	1 Each		
D5010		Motor Starter, 5-20 HP, <600 V	1975	3 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1996	2 Each		150A
D5010	PPB-DC	Power Panel Board, 208 Y/120 V, 100 Amp.	1961	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	2003	3 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1990	8 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1996	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1975	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1961	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	2000	1 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	2006	1 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1999	2 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	2004	3 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	2007	2 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	1997	9 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 100 Amp.	2008	13 Each		125A
D5010		Power Panel Board, 208 Y/120 V, 200 Amp.	1995	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 200 Amp.	1961	1 Each		175A
D5010		Power Panel Board, 208 Y/120 V, 225 Amp	2000	13 Each		
D5010		Power Panel Board, 208 Y/120 V, 225 Amp	1999	6 Each		
D5010		Power Panel Board, 208 Y/120 V, 225 Amp	1988	3 Each		
D5010		Power Panel Board, 208 Y/120 V, 225 Amp	1991	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 225 Amp	1997	14 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	2009	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	1989	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	2012	2 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	1961	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	1997	2 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	2005	1 Each		
D5010		Power Panel Board, 208 Y/120 V, 400 Amp.	2010	1 Each		
D5010		Power Panel Board, 480 V, 200 Amp.	1961	1 Each		225A
D5010		Power Panel Board, 480 V, 200 Amp.	1990	1 Each		225A
D5010		Primary Transformer, Dry, 1,000 kVA	2005	2 Each		
D5010		Primary Transformer, Dry, 1,000 kVA	1997	2 Each		
D5010		Secondary Transformer, Dry, 300 kVA	1997	1 Each		
D5010		Secondary Transformer, Dry, 50 kVA	1990	1 Each		
D5010		Secondary Transformer, Dry, 500 kVA	1997	1 Each		
D5010		Switchboard, 1600 Amp.	2005	2 Each		
D5010		Switchboard, 1600 Amp.	1997	1 Each		
D5010		Switchboard, 1600 Amp.	2009	1 Each		
D5010		Switchgear, Indoor, 600 V	1997	1 Each		
D5010	ATS-1, 2, 5, 6, 9	Transfer Switch, Auto, 600 V, 400 Amp.	1997	5 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Page 9

Unifromat	Asset Description	Component	Date	Quantity	Location	Notes
D5020		Compact Fluorescent Lighting Fixture, 32 w	1990	20 Each		
D5020		Compact Fluorescent Lighting Fixture, 32 w	2000	51 Each		
D5020		Emergency Lighting Pack, 2 Light w/ Battery	1961	2 Each		
D5020		Emergency Lighting Pack, 2 Light w/ Battery	1985	2 Each		
D5020		Emergency Lighting Pack, 2 Light w/ Battery	2000	22 Each		
D5020		Emergency Lighting Pack, 2 Light w/ Battery	2011	3 Each		
D5020		Exit Lighting Fixture, w/ Battery	1995	26 Each		
D5020		Exit Lighting Fixture, w/ Battery	2002	8 Each		
D5020		Exit Lighting Fixture, w/ Battery	1961	4 Each		
D5020		Exit Lighting Fixture, w/ Battery	1990	2 Each		
D5020		Exit Lighting Fixture, w/ Battery	2000	16 Each		
D5020		Exit Lighting Fixture, w/ Battery	2011	1 Each		
D5020		Exit Lighting Fixture, w/ Battery	2012	1 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	1961	27 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	2010	40 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	1980	68 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	2000	195 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	1995	244 Each		
D5020		Fluorescent Lighting Fixture, T8, 2-32w	2005	14 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	2011	30 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	2012	12 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	1990	153 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	2010	76 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	1985	83 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	1995	228 Each		
D5020		Fluorescent Lighting Fixture, T8, 4-32 w	2000	384 Each		
D5020		High Pressure Sodium Lighting Fixture, 250 w	1990	2 Each		
D5020		Incandescent Lighting Fixture, Basic, 100 w	1995	36 Each		AUDITORIUM SEATS
D5020		Incandescent Lighting Fixture, Basic, 100 w	2000	3 Each		
D5020		Incandescent Lighting Fixture, Basic, 100 w	1961	16 Each		
D5020		Incandescent Lighting Fixture, Basic, 100 w	1995	15 Each		
D5020		Incandescent Lighting Fixture, Basic, 100 w	2011	8 Each		
D5020		Receptacle, 120 V, 15 Amp.	1961	400 Each		
D5020		Receptacle, 120 V, 15 Amp.	1974	600 Each		
D5020		Receptacle, 120 V, 15 Amp.	1992	800 Each		
D5020		Receptacle, 120 V, 15 Amp.	2002	200 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Page 10

Unifomat	Asset Description	Component	Date	Quantity	Location	Notes
D5020		Receptacle, 120 V, 15 Amp.	2011	150 Each		
D5020		Wiring Device, Switch	1961	110 Each		
D5020		Wiring Device, Switch	1974	100 Each		
D5020		Wiring Device, Switch	1994	250 Each		
D5020		Wiring Device, Switch	2000	150 Each		
D5030		Alarm Siren	1961	4 Each		
D5030		Annunciation Panel	2000	1 Each		
D5030		Camera, Interior, Closed Circuit, Fixed Color	2000	8 Each		
D5030		Card Reader	2011	3 Each		
D5030		Card Reader	2005	46 Each		
D5030		Fire Alarm Bell, 6"	2000	2 Each		
D5030		Fire Alarm Horn & Strobe	2012	2 Each		
D5030		Fire Alarm Horn & Strobe	2011	7 Each		
D5030		Fire Alarm Horn & Strobe	1995	3 Each		
D5030		Fire Alarm Horn & Strobe	2000	115 Each		
D5030		Heat Detector	1995	6 Each		
D5030		Keypad	2000	9 Each		
D5030		Manual Pull Station	1985	2 Each		
D5030		Manual Pull Station	2000	21 Each		
D5030		Motion Detector	2012	1 Each		
D5030		Motion Detector	2011	4 Each		
D5030		Motion Detector	1980	5 Each		
D5030		Motion Detector	2000	2 Each		
D5030		Motion Detector	1995	20 Each		
D5030		Public Address Speaker	2011	12 Each		
D5030		Public Address Speaker	1990	15 Each		
D5030		Public Address Speaker	1995	42 Each		
D5030		Security System Panel	2000	2 Each		
D5030		Security System Panel	1995	1 Each		
D5030		Smoke Detector	1995	19 Each		
D5030		Smoke Detector	2000	14 Each		
D5030		Smoke Detector, Duct	1995	9 Each		
D5090		Inverter	1998	1 Each		
D5090		Inverter Battery	1998	24 Each		
D5090		Power Supply/Conditioner	2000	2 Each		
D5090		Power Supply/Conditioner	2012	2 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Page 11

Uniformat	Asset Description	Component	Date	Quantity	Location	Notes
D5090		Uninterruptible Power Supply, 30 kVA	2011	1 Each		
D5090		Uninterruptible Power Supply, 450 kVA	2010	2 Each		
D5090		Uninterruptible Power Supply, 750 KVA	2011	2 Each		
E1020		Sink, Epoxy Resin, Laboratory	2011	1 Each		

§ Indicates Component set to have PM Tasks coincide with Replacement Task.

All costs expressed in (\$) 2012.

04-Dec-13

Page 12

Average M&R Costs

Whitestone Research

	B-Central Flight Control/Range Bldg	GSFT: 113,961
Building Number:	1019/51/50	PRV: \$41,722,280
Facility:	Goddard Space Flight Center	Built Date: 1961
City:	Washington, D.C.	

M&R Average Annual Cost Forecasts

	Current Year	5 Year	20 Year	50 Year
PM & Minor Repair:	\$177,159	\$169,153	\$179,970	\$178,916
Unscheduled Maintenance:	\$117,509	\$113,883	\$122,688	\$121,170
Renewal & Replacement:	\$17,197	\$581,748	\$673,990	\$764,910
Total M&R Costs:	\$311,865	\$864,784	\$976,648	\$1,064,996
Per GSFT:	\$2.74	\$7.59	\$8.57	\$9.35
As % of PRV:	0.75%	2.07%	2.34%	2.55%

M&R Costs by System per Year Chart

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Building Num:

Facility: Goddard Space Flight Center


GSFT: 113961

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
----------------	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---

A10 Foundations																										
A20 Basement Construction																										
B10 Super Structure																										
B20 Exterior Enclosure																										
B30 Roofing	0.05	0.05	0.15	0.05	0.05	0.05	0.05	0.08	0.05	0.05	0.05	0.05	0.05	4.31	0.05	0.05	0.05	0.05	2.68	0.05	0.05	0.05	0.34	0.05	0.05	
C10 Interior Construction	0.09	0.00	0.22	0.22	0.09	0.00	0.01	0.45	1.23	0.00	0.01	0.02	0.14	0.21	0.01	0.02	0.09	0.27	1.15	0.02	0.09	0.00	0.22	2.15	0.03	
C20 Stairs	0.01					0.01				0.09					0.01			0.01		0.00			0.01		0.52	0.01
C30 Interior Finishes	0.01		1.22	0.43	6.51		0.06	2.78	1.05	0.99		0.01	1.38	0.15	1.58	0.47	0.04	1.25	1.00	2.23	0.51	0.44	3.78	14.88	1.14	
D10 Conveying	0.16	0.16	0.16	0.16	0.16	0.16	0.16	1.75	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16		
D20 Plumbing	0.09	0.17	0.70	0.14	0.43	0.15	0.12	0.44	0.14	0.19	0.14	0.12	0.19	0.12	0.13	0.22	0.09	0.68	0.11	0.23	0.10	0.13	0.81	0.35	0.14	
D30 HVAC	1.58	2.44	7.76	1.79	1.90	1.71	4.74	5.84	6.15	5.77	1.58	2.27	4.44	1.62	1.80	1.85	5.30	4.19	2.08	1.86	1.59	2.94	5.85	5.94	3.55	
D40 Fire Protection	0.07	0.07	0.12	0.08	0.12	0.07	0.07	0.40	0.07	0.26	0.07	0.07	0.08	0.07	0.07	0.08	0.19	0.50	0.07	0.26	0.07	0.12	0.07	0.07		
D50 Electrical	0.68	1.28	4.60	0.70	3.28	1.01	0.82	4.57	1.79	1.02	0.68	0.82	11.44	3.58	8.99	0.75	1.36	4.96	2.53	1.42	1.53	1.44	6.34	0.81	3.38	
E10 Equipment	0.00	0.00		0.00		0.00			0.00		0.00		0.00	0.01	0.00	0.00		0.00		0.00		0.00		0.00		
E20 Furnishings																										
F10 Special Construction																										
F20 Selective Bldg Demolition																										
G10 Site Preparation																										
G20 Site Improvements																										
G30 Site Mechanical Utilities																										
G40 Site Electrical Utilities																										
G90 Other Site Construction																										

Total	2.74	4.17	14.93	3.56	12.54	3.15	6.03	16.32	12.37	8.44	2.68	3.51	22.14	5.96	12.78	3.58	7.26	14.69	8.33	6.24	4.12	5.27	17.56	34.04	8.52
-------	------	------	-------	------	-------	------	------	-------	-------	------	------	------	-------	------	-------	------	------	-------	------	------	------	------	-------	-------	------



Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft. All costs expressed in (\$) 2012 per gsft.

Year 1-25

Based on a 50-Year Forecast.

M&R Costs by System per Year Chart

Whitestone Research

04-Dec-13


Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

City: Washington, D.C.

Building Num: 1019/51/50

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	Total	
A10 Foundations																											0.00	
A20 Basement Construction																											0.00	
B10 Super Structure																											0.47	
B20 Exterior Enclosure							0.08					0.01		1.10								0.10						19.17
B30 Roofing	0.05	0.05	1.29	0.05	0.05	0.05	0.05	1.66	0.05	0.05	0.05	0.05	0.08	0.05	0.05	0.05	0.05	0.05	0.05	0.05	0.05	2.80	0.05	0.05	0.05	0.05	3.52	
C10 Interior Construction	0.00	0.01	1.03	1.80	0.00	0.01	0.08	0.08	0.70	0.01	0.08	0.03	0.42	0.65	0.08	0.03	0.00	0.22	0.78	0.03	0.00	0.01	0.51	0.82	0.00	14.21		
C20 Stairs							0.01							0.01					0.01			0.05						0.86
C30 Interior Finishes	0.16	0.07	0.44	0.17	5.75	0.02		2.64	1.44	1.33	0.01		0.80	0.64	2.60		0.01	1.47	1.20	1.36		0.06	7.72	3.78	1.25	74.82		
D10 Conveying	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	0.16	11.03		
D20 Plumbing	0.13	0.11	0.81	0.25	0.49	0.11	0.15	0.29	0.11	0.10	0.21	0.13	0.48	0.11	0.21	0.10	0.11	0.37	0.18	0.21	0.14	0.10	0.54	0.14	0.14	11.86		
D30 HVAC	1.69	5.10	6.58	2.46	1.99	1.60	1.87	5.28	1.93	1.82	1.85	5.40	2.34	5.91	5.84	1.58	2.45	6.85	2.14	1.79	2.06	4.72	7.44	2.40	1.86	171.51		
D40 Fire Protection	0.07	0.07	0.41	0.07	0.37	0.07	0.07	0.11	0.19	0.07	0.07	0.07	0.54	0.12	0.27	0.07	0.07	0.15	0.07	0.07	0.07	0.07	0.44	0.07	0.26	7.07		
D50 Electrical	1.48	1.28	5.75	3.99	1.96	0.69	0.74	10.48	0.77	0.89	1.01	1.00	3.69	2.36	1.42	0.66	1.21	4.86	3.59	9.20	0.79	1.33	5.86	1.34	3.27	139.43		
E10 Equipment	0.00	0.00	0.01		0.00			0.00		0.00		0.00		0.00			0.00	0.00	0.01		0.00		0.00	0.00	0.00	0.05		
E20 Furnishings																											0.00	
F10 Special Construction																											0.00	
F20 Selective Bldg Demolition																											0.00	
G10 Site Preparation																											0.00	
G20 Site Improvements																											0.00	
G30 Site Mechanical Utilities																											0.00	
G40 Site Electrical Utilities																											0.00	
G90 Other Site Construction																											0.00	
Total	3.74	6.85	16.46	9.05	10.78	2.70	3.12	22.30	6.46	4.42	3.43	6.85	8.50	10.14	10.62	2.66	4.07	16.89	9.32	12.88	3.26	6.50	27.79	10.56	6.99	467.26		



Notes: A value of "0.00" means cost of more than \$.000 but less than \$.005 per gsft.

All costs expressed in (\$) 2012 per gsft.

Year 26-50

Based on a 50-Year Forecast.

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
----------------	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---

B10 Super Structure

Repair Concrete Decking (2% of Decking)							850																			
Finish Repaired Concrete Decking								40																		
Replace Concrete Decking																									42,259	
Finish Replaced Concrete Decking																									1,935	
Refinish Concrete Decking																									1,935	

B20 Exterior Enclosure

Finish Replaced Steel, Painted, Exterior Door																									41	
Repair Concrete, Cast-in-place, Painted, Exterior, 2nd Floor (2%																									512	
Replace Concrete, Cast-in-place, Painted, Exterior, 2nd Floor																										
Finish Replaced Concrete, Cast-in-place, Painted, Exterior, 2nd																										64
Finish Repaired Concrete, Cast-in-place, Painted, Exterior, 2nd																										
Maintain Aluminum Frame, Fully Glazed, Exterior Door Locks		185							185						185										185	
Replace Aluminum Frame, Fully Glazed, Exterior Door Locks									2,510																2,510	
Repair Aluminum Frame, Fully Glazed, Exterior Door									1,418																1,418	
Replace Aluminum Frame, Fully Glazed, Exterior Door																										
Maintain Steel, Painted, Exterior Door Locks		36							36							36									36	
Replace Steel, Painted, Exterior Door Locks									502																502	
Refinish Concrete, Cast-in-place, Painted, Exterior, 2nd Floor									3,152																3,152	
Repair Steel, Painted, Exterior Door									284																	
Replace Steel, Painted, Exterior Door																										1,348
Replace Steel, Painted, Exterior Double Door Locks									1,505																1,505	
Refinish Steel, Painted, Exterior Double Door									205																205	
Repair Steel, Painted, Exterior Double Door									1,590																9,036	
Replace Steel, Painted, Exterior Double Door																										205
Finish Replaced Steel, Painted, Exterior Double Door									41																41	
Refinish Steel, Painted, Exterior Double Door																										
Replace Aluminum Curtain Wall System																										
Finish Repaired Concrete, Cast-in-place, Painted, Exterior, 1st F																										64
Finish Aluminum Curtain Wall System																										
Replace Aluminum Siding, Exterior, 3rd+ Floor									46,164																	
Clean & Reseal Clay Brick, Exterior, 1st Floor									32,166																32,166	
Repair Clay Brick, Exterior, 1st Floor (2% of Walls)																										
Repoint (50% surface) Clay Brick, Exterior, 1st Floor																										
Maintain Steel, Painted, Exterior Double Door Locks		111							111							111									111	
Replace Clay Brick, Exterior, 1st Floor																										641,328

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
----------------	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---	------	---	---	---	---

B10 Super Structure

Repair Concrete Decking (2% of Decking)												850											
Finish Repaired Concrete Decking												40											
Replace Concrete Decking																							
Finish Replaced Concrete Decking																							
Refinish Concrete Decking									1,935												1,935		

B20 Exterior Enclosure

Finish Replaced Steel, Painted, Exterior Door																								
Repair Concrete, Cast-in-place, Painted, Exterior, 2nd Floor (2																								
Replace Concrete, Cast-in-place, Painted, Exterior, 2nd Floor																						23,905		
Finish Replaced Concrete, Cast-in-place, Painted, Exterior, 2n																							3,152	
Finish Repaired Concrete, Cast-in-place, Painted, Exterior, 2nd																								
Maintain Aluminum Frame, Fully Glazed, Exterior Door Locks	185											185										185		
Replace Aluminum Frame, Fully Glazed, Exterior Door Locks	2,510											2,510												
Repair Aluminum Frame, Fully Glazed, Exterior Door							1,418													1,418				
Replace Aluminum Frame, Fully Glazed, Exterior Door																						9,676		
Maintain Steel, Painted, Exterior Door Locks	36							36				36									36			36
Replace Steel, Painted, Exterior Door Locks								502				502												
Refinish Concrete, Cast-in-place, Painted, Exterior, 2nd Floor	3,152											3,152												
Repair Steel, Painted, Exterior Door												284												
Replace Steel, Painted, Exterior Door																								
Replace Steel, Painted, Exterior Double Door Locks								1,505												1,505				
Refinish Steel, Painted, Exterior Double Door								205												205				
Repair Steel, Painted, Exterior Double Door												1,590												
Replace Steel, Painted, Exterior Double Door																								
Finish Replaced Steel, Painted, Exterior Double Door								41				41												
Refinish Steel, Painted, Exterior Door																						396,285		
Replace Aluminum Curtain Wall System																							5,039	
Finish Repaired Concrete, Cast-in-place, Painted, Exterior, 1st																								
Finish Aluminum Curtain Wall System																								
Replace Aluminum Siding, Exterior, 3rd+ Floor																								
Clean & Reseal Clay Brick, Exterior, 1st Floor							32,166					32,166												
Repair Clay Brick, Exterior, 1st Floor (2% of Walls)																					12,827			
Repoint (50% surface) Clay Brick, Exterior, 1st Floor																					65,941			
Maintain Steel, Painted, Exterior Double Door Locks	111						111					111									111			111
Replace Clay Brick, Exterior, 1st Floor																								

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 1, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7	
Clean & Reseal Clay Brick, Exterior, 2nd Floor								17,615									17,615								
Repair Clay Brick, Exterior, 2nd Floor (2% of Walls)																									
Repair Concrete, Cast-in-place, Painted, Exterior, 1st Floor (2%																									736
Finish Replaced Concrete, Cast-in-place, Painted, Exterior, 1st F																									
Replace Concrete, Cast-in-place, Painted, Exterior, 1st Floor																									
Repoint (50% surface) Clay Brick, Exterior, 2nd Floor																									
Refinish Concrete, Cast-in-place, Painted, Exterior, 1st Floor																									
Replace Clay Brick, Exterior, 3rd+ Floor																									68,856
Repoint (50% surface) Clay Brick, Exterior, 3rd+ Floor																									
Repair Clay Brick, Exterior, 3rd+ Floor (2% of Walls)																									
Clean & Reseal Clay Brick, Exterior, 3rd+ Floor																5,270									
Replace Clay Brick, Exterior, 2nd Floor																									271,975

B30 Roofing

Non-Destructive Moisture Inspection, Built-up Roof w/ Cool Refle								1,528								1,528								1,528	
Replace Metal Roof																									27,152
Repair Metal Roof									617							617									
Maintain Metal Roof	301	301	301	301	301	301	301		301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	
Replace Metal Awning																	22,726								
Repair Metal Awning									3,937																
Refinish Metal Awning										3,446															3,446
Minor Replacement, Metal Roof (2% of Roof)										543															
Maintain Built-up Roof w/ Cool Reflective Coating	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	
Replace Membrane, Built-up Roof																	291,135								
Place New Membrane Over Existing, Built-up Roof																									
Non-Destructive Moisture Inspection, Built-up Roof									1,826								1,826								1,826
Maintain Built-up Roof	1,192	1,192	1,192	1,192	1,192	1,192	1,192		1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192		
Replace Membrane, Built-up Roof w/ Cool Reflective Coating																	300,302								
Place New Membrane Over Existing, Built-up Roof w/ Cool Refle																	172,394								

C10 Interior Construction

Refinish Steel, Painted, w/ Safety Glass Interior Door								125								125									125
Refinish Wood, Solid Core, Painted, Interior Door	2,768			248	2,768				248	2,768				248	2,768			248	2,768				248	2,768	
Finish Replaced Steel, Painted, w/ Safety Glass Interior Door																								125	
Replace Steel, Painted, w/ Safety Glass Interior Door																								5,452	
Maintain Wood, Solid Core, Painted, Interior Door Locks		222	2,479					222	2,479					222	2,479			222	2,479				222	2,479	
Maintain Steel, Painted, w/ Safety Glass Interior Door Locks			111						111						111				111						
Maintain Wood, Solid Core w/ Safety Glass, Painted, Interior Doo	1,701		777					1,701		777				1,701		777		1,701		777			1,701	777	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 2, Year 1-25

Based on a 50-Year Forecast.

Building: B-Central Flight Control/Range Bldg**Facility:** Goddard Space Flight Center**Building Num:** 1019/51/50**City:** Washington, D.C.

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Clean & Reseal Clay Brick, Exterior, 2nd Floor									17,615								17,615									
Repair Clay Brick, Exterior, 2nd Floor (2% of Walls)																								5,440		
Repair Concrete, Cast-in-place, Painted, Exterior, 1st Floor (2%																										
Finish Replaced Concrete, Cast-in-place, Painted, Exterior, 1st																								3,122		
Replace Concrete, Cast-in-place, Painted, Exterior, 1st Floor																								32,423		
Repoint (50% surface) Clay Brick, Exterior, 2nd Floor																								27,775		
Refinish Concrete, Cast-in-place, Painted, Exterior, 1st Floor								3,122															3,122			
Replace Clay Brick, Exterior, 3rd+ Floor																										
Repoint (50% surface) Clay Brick, Exterior, 3rd+ Floor																								6,981		
Repair Clay Brick, Exterior, 3rd+ Floor (2% of Walls)																									1,377	
Clean & Reseal Clay Brick, Exterior, 3rd+ Floor										5,270													5,270			
Replace Clay Brick, Exterior, 2nd Floor																										

B30 Roofing

Non-Destructive Moisture Inspection, Built-up Roof w/ Cool Ref		1,528					1,528						1,528					1,528						1,528			
Replace Metal Roof																											
Repair Metal Roof				617				617					617					617						617			
Maintain Metal Roof	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301	301		
Replace Metal Awning																		22,726									
Repair Metal Awning								3,937																			
Refinish Metal Awning								3,446																			
Minor Replacement, Metal Roof (2% of Roof)																		543									
Maintain Built-up Roof w/ Cool Reflective Coating	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996	996		
Replace Membrane, Built-up Roof																		291,135									
Place New Membrane Over Existing, Built-up Roof		138,056																									
Non-Destructive Moisture Inspection, Built-up Roof		1,826					1,826						1,826												1,826		
Maintain Built-up Roof	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192	1,192			
Replace Membrane, Built-up Roof w/ Cool Reflective Coating																											
Place New Membrane Over Existing, Built-up Roof w/ Cool Refl								172,394																172,394			

C10 Interior Construction

Refinish Steel, Painted, w/ Safety Glass Interior Door		125					125						125					125						125		
Refinish Wood, Solid Core, Painted, Interior Door							248	2,768					248	2,768				248	2,768				248	2,768		
Finish Replaced Steel, Painted, w/ Safety Glass Interior Door																										
Replace Steel, Painted, w/ Safety Glass Interior Door																										
Maintain Wood, Solid Core, Painted, Interior Door Locks							222	2,479					222	2,479				222	2,479				222	2,479		
Maintain Steel, Painted, w/ Safety Glass Interior Door Locks			111				111						111					111						111		
Maintain Wood, Solid Core w/ Safety Glass, Painted, Interior D		444					1,701	777					1,257	777				1,701	777				1,701	777		

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7	
Finish Replaced Steel, Painted, Interior Double Doors																									2,184
Replace Steel, Painted, w/ Safety Glass Interior Door Locks																									1,432
Replace Wood, Solid Core, Painted, Interior Door Locks								2,862	31,969													2,862	31,969		
Replace Wood, Solid Core, Painted, Interior Door																									
Refinish Wood, Solid Core w/ Safety Glass, Painted, Interior Doo	868	496		1,404	868	496		1,404	868	496	1,404	868	496	1,404	868	496	1,404	868	496	1,404	868	496	1,404	868	
Replace Wood, Solid Core w/ Safety Glass, Painted, Interior Doo							21,949	10,020														21,949	10,020		
Replace Wood, Solid Core w/ Safety Glass, Painted, Interior Doo																									
Finish Replaced Wood, Solid Core w/ Safety Glass, Painted, Inte																									
Refinish Steel, Painted, Interior Double Door		2,184			2,184			2,184			2,184			2,184			2,184			2,184			2,184		
Finish Replaced Steel, Painted, Interior Double Door w/ Safety G																									1,541
Finish Replaced Wood, Solid Core, Painted, Interior Door																									
Maintain Steel, Painted, Interior Door Locks			3,292				3,292				3,292						3,292				3,292			369	
Refinish Toilet Partitions, Painted Metal, Overhead Braced			661			661					661	661		661	661			661	661		661			661	
Replace Toilet Partitions, Painted Metal, Overhead Braced			19,772				19,772																	19,772	
Maintain Aluminum, Fully Glazed, Interior Door Locks			258				258				258			258				258						258	
Replace Aluminum, Fully Glazed, Interior Door Locks							3,339																	3,339	
Refinish Steel, Painted, Interior Door	3,263	413	3,263	413	3,263	413		3,263	413	3,263	413	3,263	413	3,263	413		3,263	413	3,263	413	3,263	413			
Replace Steel, Painted, Interior Door Locks								42,464																42,464	
Replace Steel, Painted, Interior Door																									102,972
Replace Steel, Painted, Interior Double Door Locks								12,882																12,882	
Replace Steel, Painted, Interior Double Door																									76,245
Replace Aluminum, Fully Glazed, Interior Door																									
Replace Steel, Painted, Interior Double Door w/ Safety Glass Loc																4,771								4,771	
Finish Replaced Steel, Painted, Interior Door																									3,263
Maintain Steel, Painted, Interior Double Door w/ Safety Glass Lo			594				594				594			594				594						594	
Maintain Steel, Painted, Interior Double Door Locks			999				999				999			999				999						999	
Refinish Steel, Painted, Interior Double Door w/ Safety Glass	1,541		1,541			1,541					1,541			1,541			1,541				1,541			39,976	
Replace Steel, Painted, Interior Double Door w/ Safety Glass																									

C20 Stairs

Finish Replaced Metal, Painted, Exterior Railing							103																		
Repair Metal, Painted, Exterior Railing																									161
Replace Wood, Interior Railing																									
Finish Repaired Wood, Interior Railing										18														18	
Repair Wood, Interior Railing										190														190	
Refinish Wood, Interior Railing		584			584			584			584			584			584			584			584		584
Finish Replaced Wood, Interior Railing																									
Finish Repaired Metal, Painted, Exterior Railing																									3

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 3, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg**Facility:** Goddard Space Flight Center**Building Num:** 1019/51/50**City:** Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7	
Refinish Metal, Painted, Exterior Railing																						120				
Replace Concrete, Interior Stairs																									58,128	
Repair Concrete, Interior Stairs									4,410																	
Replace Concrete, Exterior Stairs																										
Repair Concrete, Exterior Stairs										328															328	
Replace Metal, Painted, Exterior Railing								4,584																		
C30 Interior Finishes																										
Repair Carpet, Nylon 20 oz., Low Traffic (2% of Carpet)		240	1,192				240	1,903				3,095		240	1,192		240	1,903								
Repair Rubber Tile Flooring (2% of Floors)												106														
Finish Replaced Concrete, Painted Flooring																									9,552	
Replace Concrete, Painted Flooring																									85,872	
Finish Repaired Concrete, Painted Flooring								192																		
Repair Concrete, Painted Flooring (2% of Floors)								1,718																		
Refinish Concrete, Painted Flooring								9,552												9,552						
Replace Concrete Flooring																									21,125	
Repair Concrete Flooring (2% of Floors)								423																		
Replace Ceramic Tile Flooring																										
Replace Carpet, Nylon 20 oz., Low Traffic			95,152					59,622				12,040				95,152									59,622	
Replace Rubber Tile Flooring						5,343																				
Repair Access Flooring w/ Laminate, Raised (2% of Floors)		7,089										2,721		7,089	12,044										3,073	
Replace Carpet on Access Flooring, Raised			39,356				25,892	39,085				39,356			25,892										39,085	
Replace Access Flooring w/ Laminate, Raised			602,338				153,724																		354,502	136,073
Repair Ceramic Tile Flooring (2% of Floors)							774																			774
Finish Repaired Concrete, Painted Ceiling																										
Finish Repaired Wood, Finished, Interior Paneling		62							62																62	
Repair Access Flooring w/ Carpet, Raised (2% of Floors)			2,747				2,765					1,819														
Finish Replaced Metal, Painted Ceiling																									13,882	
Finish Repaired Metal, Painted Ceiling																									277	
Repair Metal, Painted Ceiling (2% of Ceiling)																									5,556	
Refinish Metal, Painted Ceiling		13,882					13,882					13,882				13,882									13,882	
Replace Metal, Painted Ceiling																									279,572	
Replace Concrete, Painted Ceiling																									181,280	
Repair Terrazzo Flooring (2% of Floors)							1,955																			
Repair Concrete, Painted Ceiling (2% of Ceiling)								10,023																		
Refinish Concrete, Painted Ceiling								94,810				74,723				83,503									28,631	
Replace Acoustical Tile, Dropped Ceiling																			3,941	219					1,493	
Repair Acoustic Tile, Dropped Ceiling (2% of Ceiling)		1,669				1,493	2,047	219	1,669																	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 4, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Task Description	Forecast Year	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	
Check & Adjust, Air Compressor, 2 HP		140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140	140		
Replace Pump & Motor Assembly, Sump Pump, 3 HP																									4,495		
Overhaul Sump Pump, 3 HP																											190
Inspect & Lubricate Sump Pump, 3 HP		94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	
Repair Air Compressor, 2 HP																											1,356
Overhaul Sump Pump, 1 HP																											572
Replace 10' Section, Pipe & Fittings, 10" Cast Iron																											936
Replace Roof Drain, 4-6"																											17,623
Maintain Roof Drain, 4-6"		1,104	1,104	1,104			1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	1,104	
Replace Sewage Ejector Pump, 1 HP																											3,580
Inspect & Lubricate Sewage Ejector Pump, 1 HP		50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	
Replace Pipe & Fittings, 4" DWV PVC (20% of Pipe)																											2,531
Replace 10' Section, Pipe & Fittings, 4" DWV PVC																											132
Replace Pipe & Fittings, 2" DWV PVC (20% of Pipe)																											7,367
Replace 10' Section, Pipe & Fittings, 2" DWV PVC																											368
Replace Pipe & Fittings, 10" Cast Iron (20% of Pipe)																											
Install New Gasket & Bolts, Pipe & Fittings, 10" Cast Iron																											144
Replace Pump & Motor Assembly, Sump Pump, 1 HP																											7,308
Replace Faucet Washer & Clean Trap, Sink, Floor		49		49		49		49		49		49		49		49		49		49		49		49		49	
Replace Valve Set, Sink, Stainless Steel						210																				210	
Repair Strainer, Sink, Stainless Steel		120				120																				1,050	
Replace Faucet Washer & Clean Trap, Sink, Stainless Steel		211	43	43	43	211	43	211	43	211	43	211	43	211	43	211	43	211	43	211	43	211	43	211	43	211	
Replace Sink, Plastic																											2,599
Replace Valve Set, Sink, Plastic																											210
Repair Strainer, Sink, Plastic																											120
Replace Faucet Washer & Clean Trap, Sink, Plastic		43		43		43		43		43		43		43		43		43		43		43		43		43	
Replace Sink, Enamaled Steel																											
Replace Sink, Stainless Steel																											6,127
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel																											154
Repair Strainer, Sink, Floor																											234
Replace Pipe & Fittings, 3/4" Copper, Hot Water (20% of Pipe)								6,541																		1,453	
Replace Valve Set, Lavatory, Vitreous China							2,101																			3,782	
Replace Washer & Spud Connection, Lavatory, Vitreous China								1,208		670								1,208		670							2,101
Replace Faucet Washer & Clean Trap, Lavatory, Vitreous Chin	423	762	423	762	423	762	423	762	423	762	423	762	423	762	423	762	423	762	423	762	423	762	423	762	423	762	
Replace Emergency Eye Wash Station																											1,464
Repack Valve Glands, Emergency Eye Wash																		50									50
Inspect & Clean Spray Heads, Emergency Eye Wash								41		41								41		41						41	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 7, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg **Facility:** Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7	
Replace Drinking Fountain, Refrigerated							22,549								22,549										
Replace Coolant & Adjust Drinking Fountain, Refrigerated		737		737		737				737		737		737		737					737		737		737
Replace Valve Set, Sink, Enameled Steel								344									344								
Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water																									570
Replace Lavatory, Vitreous China																	7,117								12,811
Replace Flush Valve, Tankless Water Closet			499				666				499				192		666								
Replace 10' Section, Pipe & Fittings, 1" Steel		192																							
Replace Pipe & Fittings, 4" Copper, Cold Water (20% of Pipe)				36,542																					1,827
Replace 10' Section, Pipe & Fittings, 4" Copper, Cold Water																									
Replace Pipe & Fittings, 2" Copper, Cold Water (20% of Pipe)					11,391																				
Resolder Joint, Pipe & Fittings, 2" Copper, Cold Water															517										517
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water							73																		327
Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pipe)		7,994																							1,453
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water							73																		400
Replace Flush Valve, Urinal, Vitreous China		2,976		915				2,976		915					2,976									915	
Resolder Joint, Pipe & Fittings, 4" Copper, Cold Water															590										590
Replace Tankless Water Closet																	11,736								15,647
Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water							147				812						147								812
Replace Urinal, Vitreous China																		5,402							17,558
Inspect & Lubricate Circulator Pump, 1/2 HP, Cold Water	141	141		141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	
Overhaul Circulator Pump, 1/2 HP, Cold Water						284					284						284								
Replace Circulator Pump, 1/2 HP, Cold Water				13,374																					13,374
Inspect & Lubricate Circulator Pump, 1/2 HP, Hot Water	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	
Overhaul Circulator Pump, 1/2 HP, Hot Water		94			94				94												94				
Replace Circulator Pump, 1/2 HP, Hot Water																	4,458								

D30 HVAC

Maintain Flash Tank, 24 Gal.	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	
Replace Pipe & Fittings, 6" Steel (20% of Pipe)																									
Replace 10' Section, Pipe & Fittings, 6" Steel				362						181					362									181	
Install New Gasket & Bolts, Pipe & Fittings, 3" Steel					100																				
Replace 10' Section, Pipe & Fittings, 3" Steel		213									213														
Replace Pipe & Fittings, 2" Steel (20% of Pipe)						264				55															67
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel					442				93	111					442								93	111	
Replace Flash Tank, 24 Gal.				886			886										886								886
Repair Flash Tank, 24 Gal.	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	
Maintain Heat Exchanger, Steam-to-Water, 25 Gpm																									

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 8, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg **Facility:** Goddard Space Flight Center
Building Num: 1019/51/50 **City:** Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	
Replace Drinking Fountain, Refrigerated		22,549										22,549											22,549			
Replace Coolant & Adjust Drinking Fountain, Refrigerated	737				737		737		737		737				737		737		737		737				737	
Replace Valve Set, Sink, Enameling Steel							344											344								
Replace 10' Section, Pipe & Fittings, 2" Copper, Cold Water																									570	
Replace Lavatory, Vitreous China																										
Replace Flush Valve, Tankless Water Closet		499					666					499				666				499					499	
Replace 10' Section, Pipe & Fittings, 1" Steel	192											192												192		
Replace Pipe & Fittings, 4" Copper, Cold Water (20% of Pipe)			36,542																						1,827	
Replace 10' Section, Pipe & Fittings, 4" Copper, Cold Water																										
Replace Pipe & Fittings, 2" Copper, Cold Water (20% of Pipe)		11,391																							400	
Resolder Joint, Pipe & Fittings, 2" Copper, Cold Water													517											517		
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Hot Water																			73					327		
Replace Pipe & Fittings, 3/4" Copper, Cold Water (20% of Pipe)	7,994																								1,453	
Replace 10' Section, Pipe & Fittings, 3/4" Copper, Cold Water																			73					400		
Replace Flush Valve, Urinal, Vitreous China			2,976		915							2,976		915					2,976		915				590	
Resolder Joint, Pipe & Fittings, 4" Copper, Cold Water															590										590	
Replace Tankless Water Closet																										
Resolder Joint, Pipe & Fittings, 3/4" Copper, Cold Water								147					812							147					812	
Replace Urinal, Vitreous China																										
Inspect & Lubricate Circulator Pump, 1/2 HP, Cold Water	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141	141		
Overhaul Circulator Pump, 1/2 HP, Cold Water			284					284					284												284	
Replace Circulator Pump, 1/2 HP, Cold Water																			13,374							
Inspect & Lubricate Circulator Pump, 1/2 HP, Hot Water	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47	47		
Overhaul Circulator Pump, 1/2 HP, Hot Water	94				94												94				94					
Replace Circulator Pump, 1/2 HP, Hot Water													4,458													

D30 HVAC

Maintain Flash Tank, 24 Gal.	41	41		41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	
Replace Pipe & Fittings, 6" Steel (20% of Pipe)													3,654												
Replace 10' Section, Pipe & Fittings, 6" Steel			362					181							362										181
Install New Gasket & Bolts, Pipe & Fittings, 3" Steel				100																					
Replace 10' Section, Pipe & Fittings, 3" Steel	213												213												213
Replace Pipe & Fittings, 2" Steel (20% of Pipe)													1,842												
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel			264																						67
Replace 10' Section, Pipe & Fittings, 2" Steel		442						93	111					442									111	93	
Replace Flash Tank, 24 Gal.			1,173															1,173							
Repair Flash Tank, 24 Gal.						886							886												886
Maintain Heat Exchanger, Steam-to-Water, 25 Gpm	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	150	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 8, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Expansion Tank, 100 Gal.																										
Maintain Expansion Tank, 100 Gal.		84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	
Replace Expansion Tank, 10 Gal.																										
Maintain Expansion Tank, 10 Gal.		84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	
Replace Condensate Receiver Station, 10-15 Gal.							19,657															19,657				
Repair Condensate Receiver Station, Motor, 10-15 Gal.														5,545												5,545
Repair Condensate Receiver Station, 10-15 Gal.														1,479		1,479		1,479		1,479						1,479
Maintain Condensate Receiver Station, 10-15 Gal.		254	254		254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	
Replace Ball Valve, 6"							21,285																			21,285
Replace Leak Detection, Panel & Float Assembly																			7,953							
Lubricate, Repack Gland, Ball Valve, 6"		1,183	1,183	1,183		1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	
Maintain Air Conditioner, Computer Room, Air-Cooled, 2 Ton		2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	
Repair Exhaust Fan, Centrifugal, 10,000 Cfm																										757
Replace Exhaust Fan, Centrifugal, 10,000 Cfm															16,734											
Maintain Exhaust Fan, Roof Mounted, 2,000 Cfm		705	705	705	705	705	705	705	353	705	705	705	705	705	705	705	705	705	705	705	705	705	705	705	705	
Repair Exhaust Fan, Roof Mounted, 2,000 Cfm															757											757
Replace Exhaust Fan, Roof Mounted, 2,000 Cfm															4,645											4,645
Maintain Variable Air Volume Box, 800 Cfm		2,578	2,578		2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578		
Replace Air Handler, Single Zone, 1,300 Cfm															9,967											9,967
Replace Variable Air Volume Box, 800 Cfm							25,196															25,196				
Repair Exhaust Fan, Centrifugal, 5,000 Cfm																757										
Repair Air Conditioner, Computer Room, Air-Cooled, 2 Ton															16,639											
Replace Air Conditioner, Computer Room, Air-Cooled, 2 Ton																			82,241							
Maintain Air Conditioner, Computer Room, Air Cooled, 3 Ton		927	927	927	927	927	927	927		927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	
Repair Air Conditioner, Computer Room, Air Cooled, 3 Ton																			6,706							
Replace Air Conditioner, Computer Room, Air Cooled, 3 Ton															30,724											
Maintain Air Conditioner, Computer Room, Air Cooled, 10 Ton		3,817	3,817		3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817		
Repair Variable Air Volume Box, 800 Cfm															3,306											
Replace Existing Ductwork (20% of Ductwork)															213,850											45,363
Maintain Air Handler, Single Zone, 2,500 Cfm		695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	
Repair Air Handler, Single Zone, 2,500 Cfm																13,499										2,935
Replace Air Handler, Single Zone, 2,500 Cfm																										13,499
Repair Air Handler, Single Zone, 10,000 Cfm															3,292										3,292	
Maintain Air Handler, Single Zone, 20,000 Cfm		1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360		
Repair Air Handler, Single Zone, 20,000 Cfm																			4,422							
Maintain Exhaust Fan, Centrifugal, 10,000 Cfm		353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	
Replace Duct Insulation (20% of Insulation)															42,834											9,698

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 9, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

		Building: B-Central Flight Control/Range Bldg										Facility: Goddard Space Flight Center														
		Building Num: 1019/51/50										City: Washington, D.C.														
Forecast Year:		2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Replace Expansion Tank, 100 Gal.																										8,176
Maintain Expansion Tank, 100 Gal.		84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	
Replace Expansion Tank, 10 Gal.							2,362																			
Maintain Expansion Tank, 10 Gal.		84	84		84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	84	
Replace Condensate Receiver Station, 10-15 Gal.								19,657																	19,657	
Repair Condensate Receiver Station, Motor, 10-15 Gal.					5,545											5,545					5,545					
Repair Condensate Receiver Station, 10-15 Gal.		1,479			1,479											1,479					1,479					
Maintain Condensate Receiver Station, 10-15 Gal.		254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	254	
Replace Ball Valve, 6"																										21,285
Replace Leak Detection, Panel & Float Assembly																										7,953
Lubricate, Repack Gland, Ball Valve, 6"		1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183	1,183		
Maintain Air Conditioner, Computer Room, Air-Cooled, 2 Ton		2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782	2,782		
Repair Exhaust Fan, Centrifugal, 10,000 Cfm																	757									
Replace Exhaust Fan, Centrifugal, 10,000 Cfm					16,734																				16,734	
Maintain Exhaust Fan, Roof Mounted, 2,000 Cfm		705	705	353	705	705	705	705	705	705	705	705	705	705	705	705	705	705	705	705	705	705	353	705	705	
Repair Exhaust Fan, Roof Mounted, 2,000 Cfm					757											757									757	
Replace Exhaust Fan, Roof Mounted, 2,000 Cfm					4,645											4,645									4,645	
Maintain Variable Air Volume Box, 800 Cfm		2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578	2,578		
Replace Air Handler, Single Zone, 1,300 Cfm																	9,967									
Replace Variable Air Volume Box, 800 Cfm							25,196																		25,196	
Repair Exhaust Fan, Centrifugal, 5,000 Cfm							757																			
Repair Air Conditioner, Computer Room, Air-Cooled, 2 Ton			16,639																						16,639	
Replace Air Conditioner, Computer Room, Air-Cooled, 2 Ton																82,241										
Maintain Air Conditioner, Computer Room, Air Cooled, 3 Ton		927	927		927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	927	
Repair Air Conditioner, Computer Room, Air Cooled, 3 Ton					30,724												6,706									30,724
Maintain Air Conditioner, Computer Room, Air Cooled, 10 Ton		3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817	3,817		
Repair Variable Air Volume Box, 800 Cfm					3,306													3,306								
Replace Existing Ductwork (20% of Ductwork)					11,017												213,850									
Maintain Air Handler, Single Zone, 2,500 Cfm		695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	695	
Repair Air Handler, Single Zone, 2,500 Cfm																2,935									2,935	
Replace Air Handler, Single Zone, 2,500 Cfm																	13,499									
Repair Air Handler, Single Zone, 10,000 Cfm					6,586											3,292					6,586				3,292	
Maintain Air Handler, Single Zone, 20,000 Cfm		1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360	1,360		
Repair Air Handler, Single Zone, 20,000 Cfm																4,422									4,422	
Maintain Exhaust Fan, Centrifugal, 10,000 Cfm		353	353	353		353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	
Replace Duct Insulation (20% of Insulation)					3,233												42,834									

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 9, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7		
Replace Exhaust Fan, Centrifugal, 5,000 Cfm						10,486																			10,486	
Maintain Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm	471	471	94	471	471	471	377	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471		
Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm						4,904				1,227														4,904		
Maintain Exhaust Fan, Centrifugal, 2,000 Cfm	1,766	1,766	1,059	1,766	1,766	1,766	1,766	707	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766			
Repair Exhaust Fan, Centrifugal, 2,000 Cfm																	1,514								2,271	
Replace Exhaust Fan, Centrifugal, 2,000 Cfm						11,613				17,419														11,613		
Maintain Exhaust Fan, Centrifugal, 5,000 Cfm	353	353		353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353		
Maintain Air Conditioner, Computer Room, Chilled Water, 5 Ton	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929		
Replace Air Handler, Single Zone, 20,000 Cfm										61,964														61,964		
Inspect & Maintain HVAC Control Panel	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608		
Repair Air Conditioner, Computer Room, Air Cooled, 10 Ton																	97,745									
Repair Fan Coil Unit, 2 Ton										2,894								3,859							2,894	
Replace Fan Coil Unit, 2 Ton						14,841												11,131							14,841	
Maintain Unit Heater, 480v, 5kW	231	231		231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231		
Repair Unit Heater, 480v, 5kW																	240									
Replace Unit Heater, 480v, 5kW						1,474																			1,474	
Replace Fan Coil Unit, 1 Ton						188,500				11,254								188,500							11,254	
Replace Direct Digital Controls, System Points										364,317								364,317								
Repair Fan Coil Unit, 1 Ton															51,036									3,048		
Minor Repair, HVAC Control Panel						2,212									2,212									2,212		
Replace HVAC Control Panel										30,988															30,988	
Maintain Thermostat	2,298	2,298	2,298	2,298	2,298	2,298	2,298	1,044	1,254	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	1,044	1,254	2,298	2,298	2,298	2,298	2,298		
Replace Thermostat								17,136	14,280									17,136	14,280							
Annual PM, Air Sample Smoke Detection System	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041			
Replace Air Sample Smoke Detection System										364,709																
Install New Gasket & Bolts, Pipe & Fittings, 6" Steel						188									94											
Monitor Direct Digital Controls, System Points	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460			
Replace Air Conditioner, Computer Room, Chilled Water, 15 To						100,657																			100,657	
Maintain Air Handler, Single Zone, 10,000 Cfm	4,083	4,083	1,360	4,083	4,083	4,083	4,083	4,083	4,083	2,722	4,083	4,083	4,083	4,083	4,083	4,083	4,083	4,083	1,360	4,083	4,083	4,083	4,083			
Repair Air Conditioner, Computer Room, Chilled Water, 5 Ton						12,534												29,339								
Replace Air Conditioner, Computer Room, Chilled Water, 5 Ton																		29,339								
Maintain Air Conditioner, Computer Room, Chilled Water, 10 To	4,771	4,771		4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771			
Repair Air Conditioner, Computer Room, Chilled Water, 10 Ton															63,071											
Replace Air Conditioner, Computer Room, Chilled Water, 10 To						232,685																			232,685	
Maintain Fan Coil Unit, 2 Ton	3,344	3,344	1,433	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344			
Repair Air Conditioner, Computer Room, Chilled Water, 15 Ton															32,925											
Replace Air Conditioner, Computer Room, Air Cooled, 10 Ton						189,901																			189,901	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 10, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

		Building: B-Central Flight Control/Range Bldg		Facility: Goddard Space Flight Center																									
		Building Num: 1019/51/50		City: Washington, D.C.																									
	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2			
Replace Exhaust Fan, Centrifugal, 5,000 Cfm																									10,486				
Maintain Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm	471	471	377	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	471	94	471	471			
Replace Fan & Motor, Exhaust Fan, Ceiling 200-500 Cfm							1,227																		4,904				
Maintain Exhaust Fan, Centrifugal, 2,000 Cfm	1,766	1,766	1,766	707	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,766	1,059	1,766	1,766	1,766	1,766	707	1,766					
Repair Exhaust Fan, Centrifugal, 2,000 Cfm									1,514																2,271				
Replace Exhaust Fan, Centrifugal, 2,000 Cfm								17,419																	11,613				
Maintain Exhaust Fan, Centrifugal, 5,000 Cfm	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353	353		
Maintain Air Conditioner, Computer Room, Chilled Water, 5 To	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929	929		
Replace Air Handler, Single Zone, 20,000 Cfm																			61,964										
Inspect & Maintain HVAC Control Panel	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608	608		
Repair Air Conditioner, Computer Room, Air Cooled, 10 Ton																			97,745										
Repair Fan Coil Unit, 2 Ton								3,859																	2,894				
Replace Fan Coil Unit, 2 Ton									11,131																	11,131			
Maintain Unit Heater, 480v, 5kW	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231	231		
Repair Unit Heater, 480v, 5kW								240																		240			
Replace Unit Heater, 480v, 5kW																			1,474									1,474	
Replace Fan Coil Unit, 1 Ton																			188,500									188,500	
Replace Direct Digital Controls, System Points							364,317												364,317									364,317	
Repair Fan Coil Unit, 1 Ton								51,036											3,048									3,048	
Minor Repair, HVAC Control Panel									2,212											2,212									2,212
Replace HVAC Control Panel																			30,988										
Maintain Thermostat	2,298	2,298	1,044	1,254	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298	2,298			
Replace Thermostat							17,136	14,280											17,136	14,280								17,136	14,280
Annual PM, Air Sample Smoke Detection System	8,041	8,041			8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041	8,041			
Replace Air Sample Smoke Detection System							364,709																					364,709	
Install New Gasket & Bolts, Pipe & Fittings, 6" Steel									188																				
Monitor Direct Digital Controls, System Points	15,460		15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460	15,460				
Replace Air Conditioner, Computer Room, Chilled Water, 15 T																			100,657										
Maintain Air Handler, Single Zone, 10,000 Cfm	4,083	4,083	4,083	4,083	4,083	4,083	4,083	1,360	4,083	4,083	4,083	4,083	4,083	4,083	4,083	4,083	4,083	4,083	2,722	4,083	4,083	4,083	4,083	4,083	4,083	4,083			
Repair Air Conditioner, Computer Room, Chilled Water, 5 Ton	12,534																		29,339									12,534	
Replace Air Conditioner, Computer Room, Chilled Water, 5 Ton																													
Maintain Air Conditioner, Computer Room, Chilled Water, 10 T	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771	4,771				
Repair Air Conditioner, Computer Room, Chilled Water, 10 Ton																			63,071										
Replace Air Conditioner, Computer Room, Chilled Water, 10 T																											232,685		
Maintain Fan Coil Unit, 2 Ton	3,344	3,344	3,344	3,344	3,344	1,911	3,344	3,344	1,433	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344	3,344				
Repair Air Conditioner, Computer Room, Chilled Water, 15 Ton																			32,925										
Replace Air Conditioner, Computer Room, Air Cooled, 10 Ton																											189,901		

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 10, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7	
Maintain Air Conditioner, DX Packaged, Air Cooled, 2 Ton		354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	
Repair Air Conditioner, DX Packaged, Air Cooled, 2 Ton																											
Replace Air Conditioner, DX Packaged, Air Cooled, 2 Ton																											
Maintain Air Conditioner, DX Packaged, Air Cooled, 5 Ton		354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	
Repair Air Conditioner, DX Packaged, Air Cooled, 5 Ton																											
Replace Air Conditioner, DX Packaged, Air Cooled, 5 Ton																											
Maintain Fan Coil Unit, 1 Ton		33,922	33,922	1,911	33,922	33,922	33,922	33,922	33,922	33,922	32,011	33,922	33,922	33,922	33,922	33,922	33,922	33,922	1,911	33,922	33,922	33,922	33,922	33,922	32,011		
Maintain Air Conditioner, Computer Room, Chilled Water, 15 To		1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908		
Replace Condenser, Air-Cooled, 2 Ton																											
Repair Circulation Pump, 5 HP, Chiller & Condenser Water																											
Replace Circulation Pump, 2 HP, Chiller & Condenser Water																											
Replace Circulation Pump, 5 HP, Chiller & Condenser Water																											
Maintain Circulation Pump, 7 1/2 HP, Chiller & Condenser Wate	225	225	225	225	225	225	225	150	225	225	225	225	74	225	225	225	225	225	225	225	225	225	150	225	225		
Repair Circulation Pump, 7 1/2 HP, Chiller & Condenser Water								579					193														386
Replace Circulation Pump, 7 1/2 HP, Chiller & Condenser Water									6,650				13,302														6,650
Replace 10' Section, Pipe & Fittings, 1" Copper																											412
Repair Condenser, Air-Cooled, 2 Ton																											1,348
Maintain Circulation Pump, 2 HP, Chiller & Condenser Water		374	374	374	374	374	374	149	374	374	225	374	374	374	374	374	374	374	374	374	374	374	374	374	374	225	
Maintain Condenser, Air-Cooled, 5 Ton		1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140		
Repair Condenser, Air-Cooled, 5 Ton																											7,256
Replace Air Handler, Single Zone, 10,000 Cfm								71,355				35,677															35,677
Maintain Flow Control Valve & Actuator, 6"		930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930		
Repair Air Handler, Single Zone, 1,300 Cfm																											2,894
Replace Flow Control Valve, Motorized, 6"																											
Resolder Joint, Pipe & Fittings, 1" Copper																											742
Maintain Condenser, Air-Cooled, 2 Ton		228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228		
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel								140																			
Repair Heat Exchanger, Steam-to-Water, 25 Gpm									891																		891
Replace Heat Exchanger, Steam-to-Water, 25 Gpm																											5,094
Resolder Joint, Pipe & Fittings, 3/4" Copper																											
Replace 10' Section, Pipe & Fittings, 3/4" Copper																											149
Replace Pipe & Fittings, 3/4" Copper (20% of Pipe)								10,207																		511	
Replace 10' Section, Pipe & Fittings, 1" Steel									301																		
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel										242																	11
Repair Circulation Pump, 2 HP, Chiller & Condenser Water											467																
Replace 10' Section, Pipe & Fittings, 4" Steel												292															
Maintain Circulation Pump, 5 HP, Chiller & Condenser Water		74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74		

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 11, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	
Maintain Air Conditioner, DX Packaged, Air Cooled, 2 Ton		354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	
Repair Air Conditioner, DX Packaged, Air Cooled, 2 Ton																											1,783
Replace Air Conditioner, DX Packaged, Air Cooled, 2 Ton																											3,900
Maintain Air Conditioner, DX Packaged, Air Cooled, 5 Ton		354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	354	
Repair Air Conditioner, DX Packaged, Air Cooled, 5 Ton																											4,267
Replace Air Conditioner, DX Packaged, Air Cooled, 5 Ton																											4,267
Maintain Fan Coil Unit, 1 Ton		33,922	33,922	33,922	33,922	33,922	33,922	33,922	1,911	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922	33,922		
Maintain Air Conditioner, Computer Room, Chilled Water, 15 T		1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908	1,908		
Replace Condenser, Air-Cooled, 2 Ton																											5,431
Repair Circulation Pump, 5 HP, Chiller & Condenser Water																											155
Replace Circulation Pump, 2 HP, Chiller & Condenser Water																											155
Replace Circulation Pump, 5 HP, Chiller & Condenser Water																											5,749
Maintain Circulation Pump, 7 1/2 HP, Chiller & Condenser Wat		225	225	74	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	225	
Repair Circulation Pump, 7 1/2 HP, Chiller & Condenser Water																											193
Replace Circulation Pump, 7 1/2 HP, Chiller & Condenser Wat																											13,302
Replace 10' Section, Pipe & Fittings, 1" Copper																											103
Repair Condenser, Air-Cooled, 2 Ton																											412
Maintain Circulation Pump, 2 HP, Chiller & Condenser Water		374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	374	
Maintain Condenser, Air-Cooled, 5 Ton		1,140	1,140		1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140	1,140		
Repair Condenser, Air-Cooled, 5 Ton																											7,256
Replace Air Handler, Single Zone, 10,000 Cfm																											71,355
Maintain Flow Control Valve & Actuator, 6"		930	930	930		930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	930	
Repair Air Handler, Single Zone, 1,300 Cfm																											2,894
Replace Flow Control Valve, Motorized, 6"																											42,973
Resolder Joint, Pipe & Fittings, 1" Copper																											742
Maintain Condenser, Air-Cooled, 2 Ton		228	228	228	228		228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	228	
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel																											140
Repair Heat Exchanger, Steam-to-Water, 25 Gpm																											891
Replace Heat Exchanger, Steam-to-Water, 25 Gpm																											5,094
Resolder Joint, Pipe & Fittings, 3/4" Copper																											149
Replace 10' Section, Pipe & Fittings, 3/4" Copper																											73
Replace Pipe & Fittings, 3/4" Copper (20% of Pipe)																											10,207
Replace 10' Section, Pipe & Fittings, 1" Steel																											149
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel																											242
Repair Circulation Pump, 2 HP, Chiller & Condenser Water																											467
Replace 10' Section, Pipe & Fittings, 4" Steel																											292
Maintain Circulation Pump, 5 HP, Chiller & Condenser Water		74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	74	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 11, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7		
Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam		360		319		360		319	880			319	880		360		319	880		360		360		880			
Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20%						4,016							1,643												1,461		
Lubricate, Repack Gland, Butterfly Valve, 4"	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360			
Replace Butterfly Valve, 4"																									7,567		
Lubricate, Repack Gland, Ball Valve, 4"	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591			
Replace Ball Valve, 4"																									6,091		
Replace Valve Actuator, 6"																											
Replace Pipe & Fittings, 1" Steel (20% of Pipe)																											
Maintain Air Handler, Multizone, 20,000 Cfm	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	2,885	1,442	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	2,885	1,442		
Repair Air Handler, Multizone, 8,000 Cfm																									4,106	4,106	
Replace Air Handler, Multizone, 8,000 Cfm																										33,677	
Maintain Air Handler, Multizone, 10,000 Cfm	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420			
Replace Pipe & Fittings, 1" Copper (20% of Pipe)																										2,061	
Replace Air Handler, Multizone, 10,000 Cfm																										40,555	
Replace Condenser, Air-Cooled, 5 Ton																										38,152	
Maintain Air Handler, Multizone, 8,000 Cfm	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078			
Replace Air Handler, Multizone, 15,000 Cfm																										109,777	
Repair Air Handler, Multizone, 10,000 Cfm																										4,277	
Repair Air Handler, Multizone, 20,000 Cfm																										6,094	12,187
Replace Air Handler, Multizone, 20,000 Cfm																										71,940	143,880
Maintain Air Handler, Multizone, 50,000 Cfm	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690			
Repair Air Handler, Multizone, 50,000 Cfm																										10,728	
Replace Air Handler, Multizone, 50,000 Cfm																										172,453	
Maintain Air Handler, Single Zone, 1,300 Cfm	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640		
Repair Air Handler, Multizone, 15,000 Cfm																										10,711	
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel																										55	
Inspect & Lubricate Circulator Pump, 1/6 HP, Chilled Water	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94		
Overhaul Circulator Pump, 1/6 HP, Chilled Water																										190	190
Replace Circulator Pump, 1/6 HP, Chilled Water																										6,226	
Maintain Air Handler, Multizone, 15,000 Cfm	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838			
Replace 10' Section, Pipe & Fittings, 1" Steel																										385	68
Replace Air Curtain, 1,000 Cfm																										1,769	1,769
Replace 10' Section, Pipe & Fittings, 2" Steel																										515	147
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel																										309	1,324
Replace 10' Section, Pipe & Fittings, 3" Steel																										132	132
Install New Gasket & Bolts, Pipe & Fittings, 3" Steel																										62	
Replace 10' Section, Pipe & Fittings, 4" Steel																										73	73

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 12, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	
Re-tape Pipe Insulation, Fiberglass, Heating Water/Steam		360		319		360		319		880				319		880		360		319		880		360		880	
Replace Pipe Insulation, Fiberglass, Heating Water/Steam (20							4,016																				1,461
Lubricate, Repack Gland, Butterfly Valve, 4"		360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	360	
Replace Butterfly Valve, 4"																											
Lubricate, Repack Gland, Ball Valve, 4"		591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	591	
Replace Ball Valve, 4"																											
Replace Valve Actuator, 6"							41,612																				41,612
Replace Pipe & Fittings, 1" Steel (20% of Pipe)																											
Maintain Air Handler, Multizone, 20,000 Cfm		4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327	4,327		
Repair Air Handler, Multizone, 8,000 Cfm																											
Replace Air Handler, Multizone, 8,000 Cfm							33,677																				33,677
Maintain Air Handler, Multizone, 10,000 Cfm		1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420	1,420		
Replace Pipe & Fittings, 1" Copper (20% of Pipe)							8,246																				2,061
Replace Air Handler, Multizone, 10,000 Cfm																											
Replace Condenser, Air-Cooled, 5 Ton							38,152																				38,152
Maintain Air Handler, Multizone, 8,000 Cfm		1,078	1,078		1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078		
Replace Air Handler, Multizone, 15,000 Cfm																											
Repair Air Handler, Multizone, 10,000 Cfm																											
Repair Air Handler, Multizone, 20,000 Cfm																											
Replace Air Handler, Multizone, 20,000 Cfm																											
Maintain Air Handler, Multizone, 50,000 Cfm		1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690	1,690		
Repair Air Handler, Multizone, 50,000 Cfm																											
Replace Air Handler, Multizone, 50,000 Cfm																											
Maintain Air Handler, Single Zone, 1,300 Cfm		640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	640	
Repair Air Handler, Multizone, 15,000 Cfm																											
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel							307																				55
Inspect & Lubricate Circulator Pump, 1/6 HP, Chilled Water		94	94		94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	94	
Overhaul Circulator Pump, 1/6 HP, Chilled Water								190																			190
Replace Circulator Pump, 1/6 HP, Chilled Water							6,226																				6,226
Maintain Air Handler, Multizone, 15,000 Cfm		2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838	2,838		
Replace 10' Section, Pipe & Fittings, 1" Steel							385																				68
Replace Air Curtain, 1,000 Cfm																											
Replace 10' Section, Pipe & Fittings, 2" Steel							515		2,212		147							515		2,212							147
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel							309																				1,324
Replace 10' Section, Pipe & Fittings, 3" Steel							132																				132
Install New Gasket & Bolts, Pipe & Fittings, 3" Steel							62																				
Replace 10' Section, Pipe & Fittings, 4" Steel								73																			73

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 12, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel																									35
Re-tape Pipe Insulation, Fiberglass, Chilled Water		120	319	120			120	319	120	1,680			319	120	1,680		120	319	120	1,680		120		1,680	
Replace Pipe Insulation, Fiberglass, Chilled Water (20% of Insul						5,714								409										1,088	409
Maintain Air Curtain, 1,000 Cfm	41	41		41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	
Replace Pipe & Fittings, 2" Steel (20% of Pipe)																									
Replace Fan & Motor, Air Curtain, 1,000 Cfm																								356	

D40 Fire Protection

Replace Gate Valve, 4"						5,347																		13,367		5,347	
Replace Pipe & Fittings, 1" Steel (20% of Pipe)																											
Replace 10' Section, Pipe & Fittings, 2" Steel						281																		281			
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel							109																	58			
Replace Pipe & Fittings, 2" Steel (20% of Pipe)																											
Replace 10' Section, Pipe & Fittings, 4" Steel						309																		309			
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel							87																	61			
Inspect & Test Fire Alarm Control Panel	268	268		268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268		
Repack Gland, Gate Valve, 4"						448																		448	179		
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel																									196		
Replace Pipe & Fittings, 4" Steel (20% of Pipe)																											
Inspect & Maintain Fire Department Connection, Siamese, 3"	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829			
Replace Fire Alarm Control Panel						5,209																		5,209			
Replace Valves & Components, Sprinkler System							5,247																				
Replace 10' Section, Pipe & Fittings, 1" Steel						246																		246			
Repair Fire Alarm Control Panel								223								223										223	
Inspect Fire Sprinkler Head	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821	821		
Test Fire Sprinkler Head							24,647		16,389															10,338	16,389		
Replace Fire Sprinkler Head																									30,283		
Maintain Fire Sprinkler System	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642			
Test Gages & Valves, Fire Sprinkler System	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512			
Replace Fire Department Connection, Siamese, 3"																											

D50 Electrical

Repair Wiring Device, Switch						23,438																				16,741
Maintain Annunciation Panel	67	67		67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67		
Replace Wiring Device, Switch						9,467																				6,942
Annual PM, Motion Detector	401	401	150	401	401	401	313	351	389	401	401	150	401	401	401	401	313	351	389	401	401	150	401	401		
Maintain Alarm Siren	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166		
Replace Alarm Siren																								763		

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 13, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel																									35
Re-tape Pipe Insulation, Fiberglass, Chilled Water		120	319	120			120	319	120	1,680			319	120	1,680		120	319	120	1,680		120		1,680	
Replace Pipe Insulation, Fiberglass, Chilled Water (20% of Ins)						5,714							409										1,088	409	
Maintain Air Curtain, 1,000 Cfm	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	41	
Replace Pipe & Fittings, 2" Steel (20% of Pipe)													2,949												
Replace Fan & Motor, Air Curtain, 1,000 Cfm													356												

D40 Fire Protection

Replace Gate Valve, 4"													13,367					5,347								
Replace Pipe & Fittings, 1" Steel (20% of Pipe)																									4,917	
Replace 10' Section, Pipe & Fittings, 2" Steel						281											281									
Install New Gasket & Bolts, Pipe & Fittings, 2" Steel							109																			
Replace Pipe & Fittings, 2" Steel (20% of Pipe)																		1,947								
Replace 10' Section, Pipe & Fittings, 4" Steel						309											309									
Install New Gasket & Bolts, Pipe & Fittings, 4" Steel							87																			
Inspect & Test Fire Alarm Control Panel	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268	268		
Repack Gland, Gate Valve, 4"					448					179															179	
Install New Gasket & Bolts, Pipe & Fittings, 1" Steel																										
Replace Pipe & Fittings, 4" Steel (20% of Pipe)																		2,540								
Inspect & Maintain Fire Department Connection, Siamese, 3"	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829	1,829			
Replace Fire Alarm Control Panel													5,209												5,209	
Replace Valves & Components, Sprinkler System						5,247																			5,247	
Replace 10' Section, Pipe & Fittings, 1" Steel						246											246									
Repair Fire Alarm Control Panel						223								223				223								
Inspect Fire Sprinkler Head	821	821	821	821	492	821	821	821	821	821	821	821	821	614	821	821	821	821	821	821	821	821	821	821		
Test Fire Sprinkler Head					24,647									14,309		16,389									24,647	16,389
Replace Fire Sprinkler Head						34,686								21,879												
Maintain Fire Sprinkler System	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642	1,642			
Test Gages & Valves, Fire Sprinkler System	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512	1,512			
Replace Fire Department Connection, Siamese, 3"													14,989													

D50 Electrical

Repair Wiring Device, Switch			10,046			6,697		7,366		16,741				10,046			6,697		7,366						
Maintain Annunciation Panel	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	67	
Replace Wiring Device, Switch			15,776			9,467				6,311		6,942			15,776			9,467							
Annual PM, Motion Detector	401	401	313	351	389	401	401	150	401	401	401	401	313	351	389	401	401	150	401	401	401	401	313	351	389
Maintain Alarm Siren	166	166	166		166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	
Replace Alarm Siren					763								763												763

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 13, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Motion Detector			18,881				6,607	3,776	944		18,881			6,607	3,776	944		18,881								
Replace Annunciation Panel			1,620															1,620								
Maintain Camera, Interior, Closed Circuit, Fixed Color		1,005	1,005	1,005	1,005	1,005	1,005	1,005		1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005		
Replace Camera, Interior, Closed Circuit, Fixed Color							21,763											21,763								
Replace Receptacle, 120 V, 15 Amp.		45,197						30,131	15,066									11,300	60,263		45,197					
Replace Card Reader			64,714					4,221			64,714							4,221			64,714					
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-32			14,393				39,712	5,203	2,081		39,538							66,590				14,393				
Replace Fire Alarm Bell, 6"							619																			
Maintain Card Reader		6,150	6,150	377	6,150	6,150	6,150	6,150	5,773	6,150	6,150	6,150	377	6,150	6,150	6,150	6,150	5,773	6,150	6,150	6,150	377	6,150	6,150		
Replace Incandescent Lighting Fixture, Basic, 100 w			11,131					655	3,491									1,746			11,131					
Replace Lamp, Incandescent Lighting Fixture, Basic, 100 w				52	410			872	137			924	410					924	274			52	410			
Replace HP Sodium Lighting Fixture, 250 w								1,096										3,063								
Replace Ballast & Lamp, HP Sodium Lighting Fixture, 250 w																										
Replace Fire Alarm Horn & Strobe			743					28,500										1,734	496		743					
Replace Fluorescent Lighting Fixture, T8, 2-32 w			66,365					71,533	7,343			3,808						10,880			66,365					
Check & Repair Manual Pull Station												2,061														
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-32			2,427					6,936			42,312						45,608	4,682		2,427						
Replace Exit Lighting Fixture, w/ Battery			13,916					8,564	2,140	4,282								1,070	535	535		13,916				
Replace Lamp, Exit Lighting Fixture, w/ Battery			2,009	558	1,003			3,125	111	111		4,911	558	1,003				4,688	447	892		2,009	558	1,003		
Replace Emergency Lighting Pack, 2 Light w/ Battery							35,401	3,218			3,218							4,828								
Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ Bat			117					176										1,290	117		117					
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/ Ba	777	2,438	777	2,438	777	2,438	777	555	2,438	777	2,438	555	2,438	777	2,438	777	2,438	444	2,438	777	2,438	777	2,438	777		
Replace Compact Fluorescent Lighting Fixture, 32 w								7,918										3,105								
Replace Fluorescent Lighting Fixture, T8, 4-32 w			62,013					104,444			22,575							62,285	8,159	3,263		62,013				
Replace Uninterruptible Power Supply, 30 kVA											46,244															
Replace Inverter Battery							9,602										9,602									
Annual PM, Inverter		1,281	1,281	1,281	1,281	1,281		1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281		
Annual PM, Power Supply/Conditioner		3,228	3,228	1,614	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228		
Replace Inverter							4,701																			
Replace Power Supply/Conditioner			84,089									84,089			84,089											
Maintain Keypad		1,129	1,129	1,129	1,129	1,129	1,129	1,129		1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129		
Replace Battery, Uninterruptible Power Supply, 30 kVA								461										461								
Replace Smoke Detector			3,452								4,685							3,452								
Maintain Uninterruptible Power Supply, 450 kVA		126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126		
Replace Uninterruptible Power Supply Battery, 450 kVA							921										921									
Replace Uninterruptible Power Supply Motor Generator, 450 kV										159,871																
Maintain Uninterruptible Power Supply, 750 kVA		126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126		

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 14, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2				
Replace Motion Detector				6,607	3,776	944		18,881				6,607	3,776	944		18,881						6,607	3,776	944						
Replace Annunciation Panel								1,620																	1,620					
Maintain Camera, Interior, Closed Circuit, Fixed Color		1,005	1,005		1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005				
Replace Camera, Interior, Closed Circuit, Fixed Color				21,763								21,763													21,763					
Replace Receptacle, 120 V, 15 Amp.					30,131	15,066							11,300	60,263		45,197									30,131	15,066				
Replace Card Reader						4,221		64,714					4,221			64,714									4,221					
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 4-3		39,712	5,203	2,081			39,538					66,590			14,393									39,712	5,203	2,081				
Replace Fire Alarm Bell, 6"				619																					619					
Maintain Card Reader		6,150	6,150	6,150	5,773	6,150	6,150	377	6,150	6,150	6,150	6,150	6,150	5,773	6,150	6,150	6,150	377	6,150	6,150	6,150	6,150	6,150	5,773	6,150					
Replace Incandescent Lighting Fixture, Basic, 100 w				655	3,491									1,746			11,131								655	3,491				
Replace Lamp, Incandescent Lighting Fixture, Basic, 100 w				872	137			924	410			924	274				52	410						872	137					
Replace HP Sodium Lighting Fixture, 250 w														3,063																
Replace Ballast & Lamp, HP Sodium Lighting Fixture, 250 w					1,096																				1,096					
Replace Fire Alarm Horn & Strobe						28,500								1,734	496		743								28,500					
Replace Fluorescent Lighting Fixture, T8, 2-32 w		71,533	7,343				3,808					10,880			66,365									71,533	7,343					
Check & Repair Manual Pull Station				2,061																				2,061						
Replace Ballast & Lamps, Fluorescent Lighting Fixture, T8, 2-3				6,936			42,312					45,608	4,682				2,427								6,936					
Replace Exit Lighting Fixture, w/ Battery				8,564	2,140	4,282						1,070	535	535			13,916							8,564	2,140	4,282				
Replace Lamp, Exit Lighting Fixture, w/ Battery				3,125	111	111		4,911	558	1,003		4,688	447	892		2,009	558	1,003						3,125	111	111				
Replace Emergency Lighting Pack, 2 Light w/ Battery				35,401	3,218		3,218					4,828												35,401	3,218					
Replace Lens, Replace Emergency Lighting Pack, 2 Light w/ B						176						1,290	117				117								176					
Replace Lamp, Replace Emergency Lighting Pack, 2 Light w/		2,438	777		555	2,438	777	2,438	555	2,438	777	2,438	777	444	2,438	777	2,438	777	2,438	777	2,438	777	555	2,438						
Replace Compact Fluorescent Lighting Fixture, 32 w					7,918							3,105												7,918						
Replace Fluorescent Lighting Fixture, T8, 4-32 w				104,444			22,575					62,285	8,159	3,263		62,013								104,444						
Replace Uninterruptible Power Supply, 30 kVA						46,244										46,244														
Replace Inverter Battery				9,602								9,602												9,602						
Annual PM, Inverter				1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281	1,281					
Annual PM, Power Supply/Conditioner				3,228	3,228	3,228	3,228	1,614	3,228	1,614	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	3,228	1,614	3,228	3,228	1,614	3,228				
Replace Inverter				4,701																				4,701						
Replace Power Supply/Conditioner						84,089		84,089									84,089		84,089											
Maintain Keypad				1,129	1,129		1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129	1,129				
Replace Battery, Uninterruptible Power Supply, 30 kVA						4,685		3,452									4,685								3,452					
Maintain Uninterruptible Power Supply, 450 kVA				126	126		126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126				
Replace Uninterruptible Power Supply Battery, 450 kVA												921																		
Replace Uninterruptible Power Supply Motor Generator, 450 k				159,871													159,871													
Maintain Uninterruptible Power Supply, 750 kVA				126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126			

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 14, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7		
Replace Uninterruptible Power Supply Battery, 750 kVA													921														921	
Replace Uninterruptible Power Supply Motor Generator, 750 kW																												
Maintain Uninterruptible Power Supply, 30 kVA		62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62		
Maintain Security System Panel								251		126				126	251					251	126					126	251	
Repair Heat Detector										517																	517	
Replace Heat Detector																												
Replace Ballast & Lamps, Compact Fluorescent Lighting Fixture,													2,701														6,887	
Replace Access Keypad													7,381														7,381	
Repair Switchgear, Indoor, 600 V (5% of total fuses)																			638									
Replace Manual Pull Station								4,859																			4,859	
Annual PM, Clean and Maintain Inverter Battery		2,620	2,620	2,620	2,620	2,620		2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620			
Replace Public Address Speaker										7,033									19,692	5,626							7,033	
Replace Smoke Detector, Duct																			7,374									
Replace Security System Panel								705					1,412						705								705	
Replace Batteries & Check Operation, Smoke Detector		1,087	1,087	626	1,087	1,087	1,087	1,087	1,087	1,087	1,087	1,087	1,087	461	1,087	1,087	1,087	1,087	626	1,087	1,087	1,087	1,087	1,087	1,087	1,087		
Replace Batteries & Check Operation, Smoke Detector, Duct		296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296		
Repair Smoke Detector								1,582										1,166								1,582		
Repair Smoke Detector, Duct									749																		749	
Check Operation, Heat Detector		249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249		
Maintain Public Address Speaker		2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,237	2,859	2,859	2,859	2,859	1,119	2,362	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,237	2,859	2,859		
Replace Disconnect Switch, 60 Amp.																			51,367	12,841							19,263	
Replace Power Panel Board, 208 Y/120 V, 100 Amp.																			19,263	57,787							19,263	
Replace Switchgear, Indoor, 600 V										7,101									12,842	6,420							7,101	
Maintain Power Panel Board, 208 Y/120 V, 100 Amp.		6,028	6,028	6,028	6,028	6,028	6,028	5,024	5,776	6,028	6,028	6,028	6,028	5,651	4,899	6,028	5,778	5,902	6,028	6,028	5,651	5,651	5,902	5,902	5,778			
Replace Motor Starter, 5-20 HP, <600 V		3,602		2,402															3,602		3,602			2,402				
Replace Coil, Motor Starter, 5-20 HP, <600 V			1,464		1,097	1,464	733	1,097	1,464	733	1,097	1,097	733	1,097	1,464	733	1,097	366	733	1,464		1,097	1,464	733	1,097			
Inspect & Clean Motor Starter, 5-20 HP, <600 V		503	755	588	755	755	755	755	755	755	755	755	755	755	503	755	755	588	755	755	755	755	755	755	755	755		
Replace Motor Control Center w/ Main Breaker, 480 V, 600 Amp								90,293										60,195								90,293		
Repair Motor Control Center w/ Main Breaker, 480 V, 600 Amp.									2,947										4,419								2,947	
Maintain Motor Control Center w/ Main Breaker, 480 V, 600 Amp		942	942	942	942	377	942	942	942	942	942	942	942	942	942	942	942	942	942	942	942	942	942	942	377			
Replace Main Switchgear, 480 V, 2,000 Amp.															765,963													
Repair Main Switchgear, 480 V, 2,000 Amp.								11,657					11,657						11,657								11,657	
Maintain Main Switchgear, 480 V, 2,000 Amp.		1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005				
Replace Disconnect Switch, 100 Amp.																											4,131	
Replace Transfer Switch, Auto, 600 V, 400 Amp.								81,084																		81,084		
Replace Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.																												
Replace Bus Duct & Fittings, AL, 800-4,000 Amp.																		254,954								152,973		

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 15, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2			
Replace Uninterruptible Power Supply Battery, 750 kVA																921												
Replace Uninterruptible Power Supply Motor Generator, 750 k						259,431																		259,431				
Maintain Uninterruptible Power Supply, 30 kVA	62	62	62		62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62	62				
Maintain Security System Panel	251	126			126	251					251	126				126	251						251	126				
Repair Heat Detector															517													
Replace Heat Detector			1,518																						1,518			
Replace Ballast & Lamps, Compact Fluorescent Lighting Fixtur			2,701												6,887										2,701			
Replace Access Keypad			7,381												7,381										7,381			
Repair Switchgear, Indoor, 600 V (5% of total fuses)											638																	
Replace Manual Pull Station							4,859																		4,859			
Annual PM, Clean and Maintain Inverter Battery	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620	2,620					
Replace Public Address Speaker		19,692	5,626												7,033					19,692	5,626							
Replace Smoke Detector, Duct			7,374																	7,374								
Replace Security System Panel			1,412				705					1,412							705						1,412			
Replace Batteries & Check Operation, Smoke Detector	1,087	1,087	461	1,087	1,087	1,087	1,087	626	1,087	1,087	1,087	1,087	1,087	1,087	1,087	1,087	461	1,087	1,087	1,087	1,087	626	1,087	1,087				
Replace Batteries & Check Operation, Smoke Detector, Duct	296	296		296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296	296				
Repair Smoke Detector			1,166												1,582										1,166			
Repair Smoke Detector, Duct															749													
Check Operation, Heat Detector	249	249		249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249	249				
Maintain Public Address Speaker	2,859	2,859	1,119	2,362	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,859	2,362	2,859	2,859	2,859	2,859	2,859	2,859	2,859				
Replace Disconnect Switch, 60 Amp.				1,219											1,219					1,219								
Replace Power Panel Board, 208 Y/120 V, 100 Amp.		83,472													51,367	12,841				19,263	57,787			12,842	6,420			
Replace Switchgear, Indoor, 600 V																					7,101							
Maintain Power Panel Board, 208 Y/120 V, 100 Amp.	4,397	6,028	6,028	6,028	6,028	6,028	6,028	6,028	6,028	6,028	6,028	6,028	6,028	5,024	5,776	6,028	6,028	6,028	5,651	4,899	6,028	5,778	5,902	6,028	6,028			
Replace Motor Starter, 5-20 HP, <600 V						1,201									3,602	3,602									1,201			
Replace Coil, Motor Starter, 5-20 HP, <600 V	1,464	733	1,097	1,097	733	1,097	1,464	733	1,097	366	733	1,464	1,097	1,464	733	1,097	1,464	733	1,097	1,464	733	1,097	1,097	733	1,097			
Inspect & Clean Motor Starter, 5-20 HP, <600 V	755	755	755	672	755	755	755	755	503	755	503	755	588	755	755	755	755	755	755	755	755	672	755	755	755			
Replace Motor Control Center w/ Main Breaker, 480 V, 600 Am						60,195									4,419									90,293				
Repair Motor Control Center w/ Main Breaker, 480 V, 600 Amp.															4,419										2,947			
Maintain Motor Control Center w/ Main Breaker, 480 V, 600 Am	942	942	942	942	942	942	942	942	565	942	942	942	942	942	942	942	942	942	942	942	377	942	942	942	942			
Replace Main Switchgear, 480 V, 2,000 Amp.									765,963																			
Repair Main Switchgear, 480 V, 2,000 Amp.			11,657												11,657					11,657				11,657				
Maintain Main Switchgear, 480 V, 2,000 Amp.	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005		1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005	1,005				
Replace Disconnect Switch, 100 Amp.						2,066													4,131									
Replace Transfer Switch, Auto, 600 V, 400 Amp.															81,084													
Replace Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.									4,437																			
Replace Bus Duct & Fittings, AL, 800-4,000 Amp.																									254,954			

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 15, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7				
Replace Bus Switch, 60 Amp.												8,415	16,831										8,415	16,831						
Maintain Circuit Breaker, 600 V, 30-60 Amp., 3 Ph.		50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50					
Repair Circuit Breaker, 600 V, 30-60 Amp., 3 Ph.							704																			704				
Replace Circuit Breaker, 600 V, 30-60 Amp., 3 Ph.																														
Repair Disconnect Switch, 100 Amp.							1,497																			898				
Repair Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.								1,406																		1,406				
Maintain Disconnect Switch, 100 Amp.		585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	585	351					
Maintain Disconnect Switch, 30 Amp.		828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828	828					
Repair Disconnect Switch, 30 Amp.							777																			777				
Replace Disconnect Switch, 30 Amp.								1,035					2,845	258	258															
Maintain Disconnect Switch, 60 Amp.		123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123	123					
Repair Disconnect Switch, 60 Amp.									263					526												263				
Maintain Power Panel Board, 208 Y/120 V, 200 Amp.		252	252	252	252	252	252	252	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100					
Maintain Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.		100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100					
Replace Switchboard, 1600 Amp.																										85,711				
Repair Power Panel Board, 208 Y/120 V, 200 Amp.									198																	198				
Repair Secondary Transformer, Dry, 300 kVA										804																804				
Repair Power Panel Board, 208 Y/120 V, 100 Amp.		593	593	198	790	2,174	2,569	395	198				593	593	198	198	395	2,569			1,581	395				593	1,778			
Maintain Secondary Transformer, Dry, 500 kVA		126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126				
Repair Secondary Transformer, Dry, 500 kVA										708																708				
Replace Secondary Transformer, Dry, 50 kVA											8,514																			
Maintain Switchboard, 1600 Amp.		166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	82	166				
Maintain Secondary Transformer, Dry, 300 kVA		126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126				
Maintain Load Bank, Indoor									628					628			628			628			628			628		628		
Maintain Switchgear, Indoor, 600 V									62					62			62			62			62			62		62		
Repair Load Bank, Indoor																				5,504										
Replace Load Bank, Indoor											192,923															192,923				
Inspect & Clean Transfer Switch, Auto, 600 V, 400 Amp.		207	207		207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207				
Repair Transfer Switch, Auto, 600 V, 400 Amp.										1,902																1,902				
Replace Secondary Transformer, Dry, 500 kVA											395			198	198	395					46,278							395		
Repair Power Panel Board, 208 Y/120 V, 400 Amp.											198			395			198					395								
Replace Power Panel Board, 208 Y/120 V, 200 Amp.												9,156				9,156														
Maintain Power Panel Board, 208 Y/120 V, 225 Amp.		4,644	4,644	4,644	4,644	4,644	4,267	4,644	4,644	4,517	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644			
Repair Power Panel Board, 208 Y/120 V, 225 Amp.										2,766			1,186	2,569							593			198			2,766			
Replace Secondary Transformer, Dry, 300 kVA																				33,195										
Maintain Power Panel Board, 208 Y/120 V, 400 Amp.		1,132	1,132	1,132	1,132	1,132	1,132	1,006	1,132	1,006	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132			
Repair Secondary Transformer, Dry, 50 kVA																										458				

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 16, Year 1-25

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

	Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2		
Replace Bus Switch, 60 Amp.							8,415	16,831								8,415	16,831									8,415	16,831	
Maintain Circuit Breaker, 600 V, 30-60 Amp., 3 Ph.	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	
Repair Circuit Breaker, 600 V, 30-60 Amp., 3 Ph.																											704	
Replace Circuit Breaker, 600 V, 30-60 Amp., 3 Ph.																												
Repair Disconnect Switch, 100 Amp.																											898	
Repair Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.																											1,406	
Maintain Disconnect Switch, 100 Amp.	585	585	585	585	585	585	585	585	468	585	585	585	585	585	585	585	585	351	585	585	585	585	585	585	585	585		
Maintain Disconnect Switch, 30 Amp.	828	828	579	828	828	828	828	704	828	828	828	828	663	828	828	828	828	828	828	828	828	828	828	828	828	787		
Repair Disconnect Switch, 30 Amp.	1,035		1,294	258	258									1,035		1,810	258	258									2,587	
Replace Disconnect Switch, 30 Amp.																											2,440	
Maintain Disconnect Switch, 60 Amp.	123	123	82	123	123	123	123	123	123	123	123	123	123	82	123	123	123	123	82	123	123	123	123	123	123	123		
Repair Disconnect Switch, 60 Amp.																											526	
Maintain Power Panel Board, 208 Y/120 V, 200 Amp.	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252		
Maintain Circuit Breaker, 600 V, 70-100 Amp., 3 Ph.	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100		
Replace Switchboard, 1600 Amp.							42,855																			42,855		
Repair Power Panel Board, 208 Y/120 V, 200 Amp.							198																				198	
Repair Secondary Transformer, Dry, 300 kVA																												
Repair Power Panel Board, 208 Y/120 V, 100 Amp.							395	1,778	395		593	593	198	790	2,174	2,569	395	198		593	593	198	198	395	2,569		1,581	
Maintain Secondary Transformer, Dry, 500 kVA	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126		
Repair Secondary Transformer, Dry, 500 kVA																												
Replace Secondary Transformer, Dry, 50 kVA																												
Maintain Switchboard, 1600 Amp.	166	125	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166	166		
Maintain Secondary Transformer, Dry, 300 kVA	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126		
Maintain Load Bank, Indoor							628				628			628			628			628			628			628		
Maintain Switchgear, Indoor, 600 V							62				62			62			62			62			62			62		
Repair Load Bank, Indoor																												
Replace Load Bank, Indoor																											192,923	
Inspect & Clean Transfer Switch, Auto, 600 V, 400 Amp.	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207	207		
Repair Transfer Switch, Auto, 600 V, 400 Amp.	1,902							1,902																		1,902		
Replace Secondary Transformer, Dry, 500 kVA																												
Repair Power Panel Board, 208 Y/120 V, 400 Amp.							198				198			198			198			198			198			198		
Replace Power Panel Board, 208 Y/120 V, 200 Amp.																											46,278	
Maintain Power Panel Board, 208 Y/120 V, 225 Amp.	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644	4,644				
Repair Power Panel Board, 208 Y/120 V, 225 Amp.	593	1,186	2,569	198										2,766		1,186	2,569									593	198	
Replace Secondary Transformer, Dry, 300 kVA																											33,195	
Maintain Power Panel Board, 208 Y/120 V, 400 Amp.	1,132	1,006	1,006	1,132	882	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132	1,132				
Repair Secondary Transformer, Dry, 50 kVA							458																				458	

Tasks ordered by UNIFORMAT II Classifications. Unscheduled Maintenance Costs are not included.

All costs expressed in (\$) 2012.

Page 16, Year 26-50

Based on a 50-Year Forecast.

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2013	4	5	6	7	2018	9	0	1	2	2023	4	5	6	7	2028	9	0	1	2	2033	4	5	6	7
Replace Power Panel Board, 208 Y/120 V, 400 Amp.						11,554		11,554								23,109									11,554
Maintain Power Panel Board, 480 V, 200 Amp.	252	252	252	252	252	252	252	126	126	252	252	252	252	252	252	252	252	252	252	252	252	252	252	252	
Repair Power Panel Board, 480 V, 200 Amp.																									198
Replace Power Panel Board, 480 V, 200 Amp.								12,355	12,355																
Maintain Primary Transformer, Dry, 1,000 kVA	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	502	1,003	1,003	1,003	1,003	1,003	1,003	502	1,003	
Repair Primary Transformer, Dry, 1,000 kVA																3,405									
Replace Primary Transformer, Dry, 1,000 kVA																	268,265								268,265
Maintain Secondary Transformer, Dry, 50 kVA	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	
Replace Power Panel Board, 208 Y/120 V, 225 Amp.						29,090		9,696								135,751		58,180	126,055						

E10 Equipment

Replace Sink, Epoxy, Laboratory																803									
Replace Faucet Washer & Clean Trap, Sink, Epoxy	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	43	
Repair Strainer, Sink, Epoxy								122																	122
Replace Valve Set, Sink, Epoxy									233																233

M&R Costs by Task

Whitestone Research

04-Dec-13

Building: B-Central Flight Control/Range Bldg

Facility: Goddard Space Flight Center

Building Num: 1019/51/50

City: Washington, D.C.

Forecast Year:	2038	9	0	1	2	2043	4	5	6	7	2048	9	0	1	2	2053	4	5	6	7	2058	9	0	1	2	
Replace Power Panel Board, 208 Y/120 V, 400 Amp.		11,554	11,554		23,109						11,554		11,554								23,109					
Maintain Power Panel Board, 480 V, 200 Amp.	252	252	252	252	252	252	252	252	252	252	252	126	126	252	252	252	252	252	252	252	252	252	252	252	252	
Repair Power Panel Board, 480 V, 200 Amp.		198	198																					198	198	
Replace Power Panel Board, 480 V, 200 Amp.												12,355	12,355													
Maintain Primary Transformer, Dry, 1,000 kVA	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	1,003	502	1,003	1,003	1,003	1,003		
Repair Primary Transformer, Dry, 1,000 kVA						3,405						3,405														
Replace Primary Transformer, Dry, 1,000 kVA																					268,265					
Maintain Secondary Transformer, Dry, 50 kVA	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	126	
Replace Power Panel Board, 208 Y/120 V, 225 Amp.											29,090		9,696								135,751		58,180	126,055		

E10 Equipment

Replace Sink, Epoxy, Laboratory		803																			803						
Replace Faucet Washer & Clean Trap, Sink, Epoxy	43	43		43		43		43		43		43		43		43		43		43		43		43		43	
Repair Strainer, Sink, Epoxy												122															
Replace Valve Set, Sink, Epoxy													233														

Operation Costs Summary

Whitestone Research

Building: B-Central Flight Control/Range Bldg

GSFT: 113,961

Building Number: 1019/51/50

Replacement Value: \$41,722,280

Facility: Goddard Space Flight Center


Building Use: Laboratory

City: Washington, D.C.

Building Type: Space Science Building

Built Date: 1961

Operation	Annual Cost/GSFT	Annual Total	Percent
Custodial	\$2.538	\$289,224	12.5%
Energy	\$2.832	\$322,757	14.0%
Grounds	\$0.126	\$14,324	0.6%
M&R	\$9.345	\$1,064,988	46.0%
Management	\$0.915	\$104,306	4.5%
Pest Control	\$0.059	\$6,675	0.3%
Refuse	\$0.033	\$3,751	0.2%
Road Clearance	\$0.015	\$1,762	0.1%
Security	\$2.300	\$262,155	11.3%
Telecom	\$1.801	\$205,290	8.9%
Water/Sewer	\$0.335	\$38,223	1.7%
Building Total	\$20.30	\$2,313,453	100.0%



Building Operations Task Details

Whitestone Research

Building: B-Central Flight Control/Range Bldg

Year Built: 1961

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/50

City: Washington, D.C.

Replacement Value: \$41,722,280

per SF: \$366

Building Gsft: 113,961

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Custodial		Level of Service: Medium			
Conference Room	49003	Vacuum Carpet with 14" Upright Vacuum	\$73,982	\$12,022	\$86,004
Office	49003	Vacuum Carpet with 14" Upright Vacuum	\$73,982	\$12,022	\$86,004
Conference Room	49003	Clean and Wipe Furniture with Trigger Sprayer & Cloth	\$28,113	\$4,568	\$32,682
Conference Room	49003	Empty Trash; Wipe Clean & Re-line Basket	\$10,569	\$1,717	\$12,286
Office	49003	Empty Trash; Wipe Clean & Re-line Basket	\$10,569	\$1,717	\$12,286
Office	49003	Clean and Wipe Furniture with Trigger Sprayer & Cloth	\$9,371	\$1,523	\$10,894
Office	49003	Dust Surfaces with Duster	\$7,046	\$1,145	\$8,191
Office	49003	Vacuum Upholstered Furniture with Tank or Canister Vacuum	\$3,610	\$587	\$4,196
Office	49003	Dust Window Blinds	\$3,382	\$550	\$3,932
Common/Circulation Are	5698	Vacuum Carpet with 14" Upright Vacuum	\$8,603	\$1,398	\$10,000
Common/Circulation Are	5698	Vacuum Upholstered Furniture with Tank or Canister Vacuum	\$1,259	\$205	\$1,464
Common/Circulation Are	5698	Empty Trash; Wipe Clean & Re-line Basket	\$1,229	\$200	\$1,429
Mechanical/Equipment R	5698	Sweep Hard Floor with 48" Push Broom	\$221	\$36	\$257
Mechanical/Equipment R	5698	Empty Trash; Wipe Clean & Re-line Basket	\$189	\$31	\$220
Auditorium	2279	Vacuum Carpet with 14" Upright Vacuum	\$3,441	\$559	\$4,000
Auditorium	2279	Pick Up Loose Debris with Lobby Pan & Porter Broom	\$2,949	\$479	\$3,428
Auditorium	2279	Vacuum Upholstered Furniture with Tank or Canister Vacuum	\$2,182	\$355	\$2,537
Auditorium	2279	Empty Trash; Wipe Clean & Re-line Basket	\$492	\$80	\$571
Restroom	1139	Service Restroom: Empty Trash, Clean & Disinfect Fixtures, Wipe Mirrors, Replace Supplies, Wet M	\$5,159	\$838	\$5,997
Restroom	1139	Service Restroom: Empty Trash, Replace Supplies & Touch Up as Needed	\$791	\$129	\$920
Break Room	1139	Empty, Clean and Disinfect Refrigerator	\$630	\$102	\$732
Break Room	1139	Damp Wipe Interior and Exterior Cupboard	\$403	\$65	\$468
Break Room	1139	Scrub and Damp Wipe Sinks	\$202	\$33	\$235
Break Room	1139	Wet Mop & Rinse Hard Floor with 32 oz. Mop Using Double Bucket & Wringer	\$189	\$31	\$220
Break Room	1139	Clean and Polish Metal Surfaces with Trigger Sprayer & Cloth	\$151	\$25	\$176
Break Room	1139	Empty Trash; Wipe Clean & Re-line Basket	\$82	\$13	\$95
Total:			\$248,794	\$40,429	\$289,224

All costs expressed in (\$) 2012.

04-Dec-13

Page 1

Functional Area	FA GSFT	Task	Labor Cost	Material Cost	Task Cost
Operation: Grounds		Level of Service: Low			
Grounds, Improved	68376	Mow Turfgrass with 21" Power Mower	\$2,587	\$1,076	\$3,663
Grounds, Improved	68376	Aerate Improved Grounds	\$1,938	\$806	\$2,744
Grounds, Improved	68376	Clear Shrubs	\$1,618	\$673	\$2,291
Grounds, Improved	68376	Edge Clean & Trim Walks with Gas Powered Edger	\$1,073	\$447	\$1,520
Grounds, Improved	68376	Overseed, Improved Grounds	\$969	\$403	\$1,372
Grounds, Improved	68376	Vacuum with 30" Billy Goat	\$647	\$269	\$916
Grounds, Improved	68376	Clear Crabgrass	\$484	\$202	\$686
Grounds, Improved	68376	Clear Weeds with 15" Boom, Improved Grounds	\$258	\$107	\$365
Grounds, Improved	68376	Trim Around Raised Objects with String Edger	\$220	\$91	\$311
Grounds, Improved	68376	Fertilize Improved Grounds	\$194	\$81	\$274
Grounds, Improved	68376	Sweep with 30" Power Rake	\$128	\$53	\$181
Grounds, Improved	68376	Fertilize Using Power Take Off Broadcast	\$0	\$0	\$0
Total:			\$10,116	\$4,208	\$14,324
Operation: Pest Control		Level of Service: Low			
Pest Controlled	113961	Install, or Check and Re-Bait 5 Rodent Boxes	\$1,789	\$744	\$2,533
Pest Controlled	113961	Inspect Building for Pests	\$2,240	\$0	\$2,240
Pest Controlled	113961	Perform Crawling Insect Abatement	\$1,343	\$559	\$1,902
Total:			\$5,372	\$1,303	\$6,675
Operation: Road Clearance		Level of Service: Medium			
Pavement NASA	91168	Plow Paved Area	\$1,354	\$408	\$1,762
Total:			\$1,354	\$408	\$1,762
Operation: Security		Level of Service: High			
Secured Area	113961	Guard Lobby/Parking	\$167,481	\$27,216	\$194,697
Secured Area	113961	Patrol Building Perimeter	\$28,890	\$4,695	\$33,585
Total:			\$196,372	\$31,910	\$228,282

Building Operations Utility Details

Whitestone Research

Building: B-Central Flight Control/Range Bldg

Year Built: 1961

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/50

City: Washington, D.C.

Replacement Value: \$41,722,280

per SF: \$366

Building Gsft: 113,961

	Utility	GSFT	Demand	UM	Rate	Cost
Operation: Energy	Level of Service: Medium					
	Electricity	113961	29.949	kWh	\$0.0820	\$279,866
	Natural Gas	113961	0.724	Thm	\$0.5200	\$42,891
	Diesel	113961	0.000	Gal	\$3.3400	\$0
	Total:		30.673			\$322,757
Operation: Refuse	Level of Service: Medium					
	Municipal Solid Waste	113961	0.370	Lbs	\$0.0711	\$2,998
	Recycling	113961	0.180	Lbs	\$0.0367	\$753
	Total:		0.550			\$3,751
Operation: Water/Sewer	Level of Service: Medium					
	Sewer	113961	18.920	Gal	\$0.0092	\$19,837
	Water	113961	24.080	Gal	\$0.0067	\$18,386
	Total:		43.000			\$38,223

Building Operations Management Details

Whitestone Research

Building: B-Central Flight Control/Range Bldg

Year Built: 1961

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/50

City: Washington, D.C.

Replacement Value: \$41,722,280 **per SF:** \$366

Building Gsft: 113,961

	Service	Demand	UM	PRV	Cost
Operation: Management	Level of Service: Low				
	Management	0.3%	PRV	\$41,722,280	\$104,306
	Total:				\$104,306

Building Operations Service Details

Whitestone Research

Building: B-Central Flight Control/Range Bldg

Year Built: 1961

FTEs: 228

Building Type: Space Science Building

Facility: Goddard Space Flight Center

Original Cost: \$1

Building Num: 1019/51/50

City: Washington, D.C.

Replacement Value: \$41,722,280

per SF: \$366

Building Gsft: 113,961

	Service*		Quantity	Rate	Cost
Operation: Security	Level of Service: High				
	Intrusion Detection Systems		3	\$4,986	\$14,958
	System Monitoring		3	\$3,615	\$10,845
	Access Control		3	\$2,690	\$8,070
	Total:				\$33,873
Operation: Telecom	Level of Service: High				
	Local Telephone		228	\$468	\$106,704
	Data		228	\$3,588	\$54,810
	Long Distance Telephone		228	\$192	\$43,776
	Total:				\$205,290